Measurement conditions

Use the recorded value only when the instrument is calibrated.

Keep the original units.

Keep the original units.

Comparison conditions

Compare two trials only if their temperatures match.

A missing measurement is not a zero.

The order of the two trials matters.