

DEMO DOCUMENT — MINE SAFETY INSPECTION REPORT

Synthetic test document for KhanDrishti OCR and document-governance workflow validation. Not an authentic government or mining-company record.

1. Mine and Inspection Details

Field	Value
Mine Name	Mine C - Singrauli Block-B
Mine Code	MINE-C
Subsidiary	NCL
District	Singrauli
State	Madhya Pradesh
Inspection Number	INSP-DEMO-2026-009
Inspection Date	08 September 2026
Inspection Type	Routine Field Safety Inspection
Inspector	R. Kumar
Location	24.2012 N, 82.6644 E

2. Inspection Observations

Observation 1 — Ventilation: Elevated methane concentration was recorded near the ventilation shaft. The recorded reading was 1.45 percent methane in the return airway. The area was marked for immediate review by the safety team.

Observation 2 — Personal Protective Equipment: Certified flameproof helmets and multi-gas detectors were not available in the seam extraction area at the time of inspection.

Observation 3 — Inspection Records: Field safety logs for the current reporting period were incomplete. The responsible team was instructed to submit the pending records.

3. Potential Compliance References

Reference	Potential Relevance	Review Status
Coal Mines Regulations, 2017	Ventilation and mine-air safety requirements	Human review required
Coal Mines Regulations, 2017	Personal protective equipment and worker safety	Human review required

4. Corrective Actions

Action	Responsible Team	Target
Review ventilation condition and methane reading	Mine Safety Team	Immediate
Provide required protective equipment	Mine Operations	Within 24 hours
Complete pending field safety logs	Inspection Team	Within 24 hours

5. Governance Processing Note

This synthetic document is intended to test PDF upload, OCR, structured field extraction, potential regulation matching, human verification, governance-record creation, risk/SLA processing, and audit logging. Extracted information must be verified by an authorized official before consequential action.