

Motor Vehicle Repair History

Agency: **Department of Information and Communications Technology**
 Province: **Cagayan Provincial Operations Office, Luzon Cluster 1**
 Type: **Single Cab Pick-Up Truck** Brand/Model: **TOYOTA HI-LUX**
 Engine No: **3L-3128241** Plate Number: **SDN 321**

Date	Nature of Repair	Purchased items			
		Description	Unit	Quantity	Price
10-Jan-19	Engine maintenance	Fan belt	pcs	2	
	Replacement of 2 pcs fan belts & radiator lower hose.	Radiator hose	pc	1	
21-Jan-19	Replacement of fuel hoses	Fuel hose	feet	4	
31-Jan-19	Repair of starter motor	Carbon brush	set	1	
	Replacement of carbon brush				
18-Aug-20	Repair of airconditioning unit	O-ring	pcs	12	
		Capella oil	bottle	1	
		Filter drier	piece	1	
		Flushing	can	4	
		Pressure switch	piece	1	
		Compressor	unit	1	
		Auxilliary fan	piece	1	
		Evaporator	assembly	1	
		Condenser	assembly	1	
		Fan belt	piece	1	
		Relay set	unit	1	
		Freon charging	lot	1	
		Labor	lot	1	
18-Aug-20	Replacement of starting battery	3SM Battery, maintenance free	unit	1	
9-Sep-20	Body repair	Repair & sectioning of the main cab flooring, primer & undercoat of the sectioned parts			
		Repair & upholstery of dilapidated seat	lot	1	
		Repair & painting of hood	lot	1	
11-Sep-20	Replacement of worn-out alternator	Alternator belt	pieces	2	
	belts				
7-Oct-20	Replacement of defective alternator unit assembly	Alternator Unit assembly	unit	1	

Date	Nature of Repair	Purchased items			
		Description	Unit	Quantity	Price
7-Oct-20	Replacement of defective alternator unit assembly	Labor for replacement, installation & rewiring		1	
27-Oct-20	Replacement of defective oil feed	Alternator hose	pc	1	
	line (alternator hose).				
3-Nov-20	Repair of airconditioning system	A/C induction switch	pc	1	
29-Dec-20	Replacement of worn-out	Clutch master assembly	set	1	
	clutch master & secondary	Clutch secondary assembly	set	1	
	assembly	Labor for repair	lot	1	
9-Mar-21	Engine change oil & other maintenace	Diesel oil	liters	6	
	jobs	Oil filter	piece	1	
		Fuel filter	piece	1	
		Replacement of fuel filter	piece	1	
		Adjustment of belts	lot	1	
23-Mar-21	Repair of alternator mounting,	Aircon belt	piece	1	
	replacement of belt tensioner	Tensioner bearing	piece	1	
	bearing & aircon compressor belt	Labor	lot	1	
2-Jun-21	Replacement of damaged/fried	Alternator Unit assembly	unit	1	
	alternator unit assembly				
23-Aug-21	Repair of fuel system	Fuel filter	piece	1	
26-Oct-21	Repair of radiator unit	Repair, cleaning & overhauling of	lot	1	
		radiator unit			
7-Dec-22	engine repair and brake system repair	valve cover gasket	pc	1	
		silicon gasket	pc	1	
		timing belt	pc	1	
		timing belt tensioner	pc	1	
		Brake master assembly	pc	1	
		brake fluid	liter	1	
		motor oil 15w40	liter	7	
		oil filter	pc	1	
		Labor for the following items			
		Replace valve cover gasket	lot	1	

Date	Nature of Repair	Purchased items			
		Description	Unit	Quantity	Price
7-Dec-22	engine repair and brake system repair	replace timing belt	lot	1	
		change oil and filter	lot	1	
		replace brakemaster assembly	lot	1	
12-Dec-22	Airconditioning system repair	freon	pc	1	
		oil	pc	1	
		oring	pc	8	
		Auxillary Fan	pc	1	
		airduct hose	pc	4	
		Labor	lot	1	
3-Feb-23	Radiator Repair	Radiator Overhaul adn services	lot	1	
25-Aug-23	Clutch System repair	Pressure plate	pc	1	
		Clutch Disc	pc	1	
		Release Bearing	pc	1	
		Pivot Bearing	pc	1	
		Labor	lot	1	
24-Oct-23	Replacement of starting Battery	3SM Battery	pc	1	

I hereby certify that the above listed were the repairs actually undertaken as of _____ that is based on the submitted "Vehicle Monthly Repair Log" and on available records in this office.

Ronald S. Bariuan
OIC, Motor Pool Unit