

Motor Vehicle Repair History

Agency: **Department of Information and Communications Technology**
 Province: **Tuguegarao City, Cagayan**
 Type: **WAGON** Brand/Model: **TOYOTA REVO**
 Engine No: **7K0648506** Plate Number: **SJN 940**
 Chassis No: **KF82-6006245** Year Model: **2004**

Date	Nature of Repair	Purchased items			
		Description	Unit	Quantity	Price
17-Dec-25	Fuel Filter	Fuel Filter	1.0	pc	₱860.00
	Brake Repair	Brake master assembly	1.0	pc	₱2,800.00
		Brake Cleaning	1.0	lot	₱1,800.00
		Brake Pads (Front&Rear)	1.0	set	₱1,850.00
	Clutch Repair	Clutch Master Assembly	1.0	set	₱2,600.00
		Secondary Cluth Master assembly	1.0	set	₱1,800.00
	Change Oil	synthetic oil (5Liters)	1.0	liters	₱2,800.00
	Oil filter	Oil filter	1.0	pcs	₱650.00
	Alternator Belts	Alternator Belts	3.0	pcs	₱1,350.00
	Coolant	Coolant (4Liters)	1.0	liters	₱880.00
	wiper blades	wiper blades	1.0	pair	₱750.00
	starter pull out repair	starter pull out repair	1.0	lot	₱1,800.00
	Radiator Over-hauling and Cleaning	Radiator Over-hauling and Cleaning	1.0	lot	₱2,000.00
	Fuel Tank Cleaning (Pull out & Pull in)	Fuel Tank Cleaning (Pull out & Pull in)	1.0	lot	₱2,500.00
	Rear door Glass Replacement	Rear door Glass Replacement	1.0	lot	₱5,500.00
	Labor	Over-all Labor	1.0	lot	₱10,200.00
23-Dec-25	Battery Replacement	BATTERY 3SM	1.0	pc	₱8,300.00
16-Jan-26	Aircon repair	Compressor	2.0	pc	₱18,000.00
		Condenser	2.0	pc	₱8,500.00
		Expansion Valve	2.0	pc	₱13,000.00
		Filter Dryer	2.0	pc	₱950.00
		Aircon Service Labor	1.0	lot	₱8,500.00
5-Feb-26	Replacement of Main Pulley Assy	Main Pulley Assy	1.0	pc	₱2,300.00
		Labor	1.0	lot	₱500.00
27-Feb-26	Repair/Replacement	T-fitting	1.0	pc	₱180.00
		Speedometer Cable	1.0	pc	₱550.00
		Brake Fluid	1.0	pc	₱200.00

Date	Nature of Repair	Purchased items			
		Description	Unit	Quantity	Price
3-Mar-26	Hydraulic Brake repair	hydraulic brake	1.0	pc	₱250.00
		Brake Fluid	1.0	pc	₱350.00
3-Mar-26	Repair/Replacement	Starter Bushing			
		Brake adaptor replacement	1.0	lot	₱1,650.00
		Bulb replacement			
10-Jun-26	Tubeless tire replacement	185 R14C 102/1000	4.0	pcs	₱14,976.00
19-Jul-24	Change oil	Gasket Drain plug	Pc	1	₱665.00
		Filter Oil	Pc	1	₱750.00
		Filter A/C Fresh Air	Pc	1	₱1,500.00
		Filter Air Cleaner	Pc	1	₱2,180.00
		Universal Cleaner	Pc	1	₱500.00
		Engine Oil	Pcs	9	₱600.00
24-Jul-24	Replacement of front break pads	Brake Pad Front	Pc	1	
	Replacement of left rear tail light	Tailight (LEFT)	Pc	1	₱4,500.00
16-Oct-24	Replacement of left rear tail light	Labor	lot	1	₱2,000.00
28-Oct-24	Body Repair	Body repair and repainting	lot	1	₱9,700.00
3-Dec-24	40k Preventive Maintenance	Filter Oil			₱720.00
		Engine Flush	PC	1	₱600.00
		Universal Cleaner	BTL	2	₱385.00
		Winshield Washer (40ML)	BTL	1	₱200.00
		Diesel Smoke Stop	BTL	1	₱750.00
		Gasket Drain plug	BTL	2	₱630.00
		Aircon Cleaner and Disinfect	PC	1	₱650.00
		Filter A/C Fresh Air	ASY	1	₱1,500.00
		Anti Freeze	PC	1	₱1,800.00
		Engine oil	LTR	8	₱600.00
		Miscellaneous	UN	1	₱448.00
17-Feb-25	Battery Replacement	Battery DIN 80	Unit	1	₱9,500.00

I hereby certify that the above listed were the repairs actually undertaken as of _____ that is based on the submitted "Vehicle Monthly Repair Log" and on available records in this office.

Ronald S. Bariuan

OIC, Motor Pool Unit