

BodyShop Auto Inc.

1847 Industrial Parkway, Springfield, MA 01104 · Tel (413) 555-0144
Plymouth Rock Approved Panel Vendor — Vendor ID PR-AV-4471

VEHICLE DAMAGE ESTIMATE

Estimate Number: EST-2026-04471-A **Date Prepared:** April 19, 2026
Prepared By: T. Hendricks, Shop Manager
Customer Reference: O'Donnell, M.
Claim Reference: CLM-2026-04-8821 (Plymouth Rock Assurance)
Vehicle: 2023 Honda CR-V Hybrid Touring · Lunar Silver Metallic

DAMAGE ASSESSMENT

Severe hail damage. Multi-panel paintless dent repair (PDR) required with partial paint refinish.
Total damage documented: 285+ dents across hood, roof, trunk lid, and quarter panels. Windshield intact.

LINE ITEMS

Roof panel paintless dent repair (140+ dents)	\$4,250.00
Hood paintless dent repair (60+ dents)	\$1,875.00
Trunk lid PDR (45+ dents)	\$1,400.00
Right rear quarter panel PDR (22 dents)	\$675.00
Left rear quarter panel PDR (18 dents)	\$625.00
Roof rail / trim removal & reinstall	\$385.00
Hail damage inspection & documentation	\$200.00
Detail / wash post-repair	\$125.00

Subtotal — Parts & PDR Labor **\$9,535.00**

PAINT REFINISH (where PDR insufficient)

Hood — blend & clear (full panel)	\$1,250.00
Roof — partial respray section	\$1,850.00
Paint & refinishing materials	\$785.00

Subtotal — Paint **\$3,885.00**

Shop Labor (12.4 hrs @ \$96/hr)	\$1,190.40
Tax (MA, on parts & materials)	\$237.10

ESTIMATE TOTAL **\$14,847.50**

*Estimate valid 30 days from date prepared.
Insured deductible per Plymouth Rock policy: \$500.00 (collected at delivery).*

T. Hendricks
Shop Manager, BodyShop Auto Inc.
Tel (413) 555-0144