# **RELEASE NOTES**

## Release Notes for PathPilot® v2.0.3

April 2018

## **Fixed Issues**

### AII

• In the **Tool Table** window, we fixed an issue where pressing **ENTER** on the keyboard's numeric keypad added a new line instead of saving your edits (PP-2010)

## Mill

• The USB interface chip for the PCNC 440® Automatic Tool Changer (ATC) was discontinued, so we added support for its replacement (PP-2081)