RELEASE NOTES

Release Notes for PathPilot® v2.0.4

April 2018

Fixed Issues

Mill

• Fixed additional issues in relation to the new PCNC 440® Automatic Tool Changer (ATC) USB interface chip.