Verification Strategy:

For Task 2:

- 1. In the watch window, add variables led_display and digit_num.
- 2. Test all values of digit_num with all bytes in led_display set to zero
- 3. Repeat for all bytes in led_display set to \$FF