

Dame Meg Hillier Chair of the Public Accounts Committee House of Commons

12 January 2023

Dear Dame Meg,

I am writing further to my letter of 22 December, which provided the Committee with information on incidents since March last year.

I have today been informed of an asbestos-related incident which took place in December in Fielden House and is currently under investigation. I have therefore updated the table I sent you last month, which is included below. Further information will be provided when available.

Yours sincerely,

Sir John Benger

Clerk of the House of Commons



| Date | Location | Incident | Action |
|---------------|----------------------|---|--|
| October 2022 | Norman Shaw North | Asbestos containing materials discovered during ground excavation works and moved without necessary precautions to prevent fibre release. Risk of exposure judged to be "very low" and incident does not meet the criteria for reporting under RIDDOR Regs Incident happened within the confines of the CDM2¹ area, with no interface with any house staff or teams | Works stopped and Principal Contractor undertook immediate investigation - Area sealed while arrangements for removal made - Incident being treated as high potential near miss - Strategic Estates as the CDM Client have ensured a comprehensive investigation has been undertaken by all parties and that the Principal Contractor has actioned the relevant findings and updated their arrangements to ensure continued site safety. |
| December 2022 | Fielden House | An inspection hatch was cut into a ceiling without appropriate controls in place. Asbestos insulation lagging debris and insulation to pipework and associated intrusions was found within the ceiling void. There does not appear to have been contamination of the area and it is expected the risk of exposure to persons is low. | I have initiated a comprehensive investigation, to establish the facts, verify the initial assessment and examine the root and underlying causes. |

_

 $^{^{\}rm 1}$ CDM refers to the Construction (Design and Management) Regulations 2015.



Fire incidents

| Date | Location | Incident | Action |
|------------------|--------------------------|---|---|
| October | Portcullis | Overheating Aquavac | Dealt with by contractors |
| 2022 | House | | |
| November 2022 | Norman Shaw North | Steam cleaning machine caught fire on scaffolding | Dealt with by Contractors |
| December 2022 | Palace of Westminster | Overheated fan belt | Investigated by in house mechanical engineers |
| December | 1 | Item of clothing left on | Removed by Fire Protection Team, |
| 2022 | Parliament | portable heater | left with In House electrical |
| | Street | | engineers |

Stone masonry falls
There have been no reported incidences of stone masonry falls since 29 March 2022.