
Process Name/ Title: Document No: WI-PRO-ASY-185 REPLENISH PROCEDURE WORK INSTRUCTION March 19, 2025 Effective Date: Product Code/Name Customer Code: Page No.: Rev. No.: 1 of 4 LEVERCON/HAZARD/STEERING TRP/NBC Records/Remarks/ Work Procedure/ Illustration PIC No. **Quality Pointers** A. Issuance of Replenish A1. LEVERCON In-process NG (whole set), Previous process NG ⇑ No. No. of Box Downtime Abrorma by Action Taken Duration PC Line Leader/Senior Leader Remarks Leader / Wrong method of insertion CP, 00,RP 9:50 10:00 10 April 1 on DOR the NG details Senior Leader 17853 **QR Code Checker** Get the ID tag of affected model on box with lacking or defect 2 encountered. Open the QR Code **Production TAG** Checker (POKAYOKE) in the Desktop **Verification TAG** Scan the Production ID tag and the verification tag (QR Code at the Leader / 3 model label in the replenish rack) to GOOD Senior Leader Note: Only Leaders and NO GOOD verify if the product that Senior Leader are allowed to will be issued is correct. reset the code. If mis-match Leader will reset by scanning Poka Yoke Pin Code and check again Green light (GOOD) would mean matching is okay Leader / 4 Get Replenish in the drawer Senior Leader REPLENISH MONITORING Model Code Fill up replenish monitoring Leader / Note: Include reason at the 5 (F-PRO-COM-005B) remarks provided Senior Leader 10 - 1 = 9 Subract remaining stocks from the qty to be issued to get the end stocks Leader / 6 Put Replenish Marking Refer to WI-ENG-PDE-002 NOTE: for levercon models only Senior Leader Prepare Check Approve Quimo K.Aquino Additional page for steering replenish procedure K.Aquino 6/24/2024 Initial issue W. Habla K.Aquino W. Carbillor Details of change Revise Check Approve Est. date: June 24, 2024 Eff./Rev. Date Rev. No.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.



CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.



	Process Name/ Title:			WI-PRO-ASY-185			
1	REPLENISH PF	Document N	lo:				
	WORK INSTE	RUCTION	Effective Date:		March 19, 2025		
	Product Code/Name:	Customer Code:	Pov. No :	4	Page No :	3 of 1	

	LEV	Product Code/Name: ERCON/HAZARD/STEERING	Customer Code: TRP/NBC	Rev. No.:	1	Page No.:	3 of 4
No.		Work Procedure/ Illus	tration	PIC	l .	Records/Remarks/ Quality Pointers	
16	Get the ID tag of affected model on box with lacking o defect encountered. Open th QR Code Checker (POKAYOKE) in the Deskto	Production		Leader / Senior Leader			
17	Scan the Production ID tag a the verification tag (QR Cod at the model label in the replenish rack) to verify if th product that will be issued is correct.	QR Code Checker	REPLENISH 17/796-7051 (Japan Connector) NO GOOD Production TAG 7m0531-7020a 36 3979 Verification TAG 7m0522-7020b If mis-match Leader will reset by scamming Poka Yoke Pin Code and check again		Leader / Senior Leader Senior Leader are allowed to reset the code.		
18	Get Replenish in the drawe		PORA VORA	Leade Senior Le			
19	Fill up replenish monitoring (F-PRO-COM-005B)	Model Code: 75N758-0022		Leade Senior Le			de reason at the is provided
20	Conduct Inspection	Leader must compare r	eplenish product vs master sample	Leade Senior Le			
21	Fill up replenish tag monitorin (F-PRO-COM-005A)	Budada	TAG MONITORING New Page Dos Relamed B Relamed by Remains Februry 8, 2004 Ge Fill up once the replemish tag return.	Leade Senior Le		replenish tag detected, che on scan data t in the wareho	nthly inventory of If a missing tag is the affected box to see if it is already use; if so, sort the ted model
22	Put REPLENISH TAG CLIP affected product, place on the affected box then put REPLENISH TAG outside the box together with the ID TAG. * Record qty. of replenish an NG in ID tag of affected box then remarks on DOR the Nedetails.	REPLENISH STITE ING 05	Note: Make sure that replenish tag number was tally on the replenish tag attached on box REPLENISH TAG STEERING OS STEERING OS	Leade Senior Le		in-line * Count the inside the b	icable in replenish. qty. of harness ox affected after olenish

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

		Process Nar	ne/ litle:	REPL	LENISH	PROC	EDURE			Document No: WI-PRO-ASY-1				
	DU		Decade at Ocal	WORK INSTRUCTION oduct Code/Name: Customer Code:							Effective Date:		March 19, 2025	
			CON/HAZA		RING			Customer Code TRP/NBC	:	Rev. No.:	1	Page No.:	4 of 4	
No.		•	Work	Procedu	ure/ Illu	ıstratio	n			PIC	;	Records/Remarks/		
C. FOR	R QC REQUEST											Quality Pointers		
23	QC will fill in Rep (F-PRO-COM photocopy th	-011) and	Marie Programme And Programme						Production Lead Sr. Lea	der	*Make sure ID tag copy is clear for scanning purpose.			
24	Process owner wi sign the request to F-PRO-COM	ag and fill up (M-005C)	Refer to GL-PRO-COM-023						Production Leader					
LEVER	CON/HAZARD (ONLY PROCE	SS OWNER	R (Control	of Rep	lenish)				1		1		
	Monitor the remaining quantity of Replenish in the Replenish Monitoring(F-PRO-COM-005B).													
	1.a . Fast moving / High volume model- Maximum qty. 10 pcs. If qty. 5 ≤ (Equal or less than) immediately request additional replenish.													
1	1.b . Slow moving / Low volume model- Maximum qty. 5 pcs. If qty. 2 ≤ (Equal or less than) immediately request additional replenish								Leader /Se		N/A			
	REPLENISH MONITORING 17.1796-7051 REPLENISH MONITORING													
	Model Code:	Qty	Qty Peggs	ested by	Box no.	Qty.	Replenished	by Rem	arks					
	May 10,2024	tart of the Shift End of	tne Snirt	QC	1234	5	МПСН	-,						
	,,		-											
	Request the lacking replenish based on the maximum and minimum stock,follow Replenish Flow Procedure(GL-PRO-COM-023). Record the request replenish in Replenish Stock Request Monitoring(F-PRO-COM-005C).											NOTE : Lead time to close the requested replenish is		
	F-PRO-COM-905C-1 EFF-03/01/19								Lead	n 7 days.				
2	REPLENISH STOCK REQUEST MONITORING						Senior L		* Follow up previous process for the status of Requesting replenish					
		Date Requeste		Requested		Receive	ed by :	Date Received by: (Section/Process)	Remarks			through email and meeting		
		5 07/24/202	_	_										
	17,796-7051	May 10,2024	May 17,2024	МТО	н									
	Note : Fill up this part upon receiving the replenish													

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.