

No.

/ire Cutting and Crimping /				
Wire Cutting and Crimping /				
Use of Air Gun and Cleaning Cabinet				

Document No:

Effective Date:

WI-PRO-CNC-032

July 10, 2017

WORK INSTRUCTION

Product Code/Name:

ALL

Customer Code: ALL

Work Procedure/ Illustration

Rev. No.:

0

Page No.:

Page 1 of 1

Records/Remarks/


Quality Pointers

Before Cleaning

1. Wear Safety goggles.



2. Open the air supply by rotating the knob counterclockwise.



3. Put parts properly inside the cleaning cabinet.



After Cleaning

1. Put the air gun and safety goggles back to its designated location.



2. Close the air supply by rotating the knob clockwise.

Before leaving the production area:

1. Clean the area (floor and cabinet)

NBC (Philippines)
MASTER COPY

							Prepare	Check	Approve
							Charcia /	OMERIN	T. SUGIYAMA
Eff./Rev.Date	Doc/DRCN No.	Rev. No.(if applicable)	Details of change	Revise	Check	Approve	Est. date:	07/10/2017	