


				WORK INS	Effectivity Date:	October 09, 2024				
			Process Name/Title:		G ASSEMBLY PROC	Validity Date:		October 09, 2024 n/a		
			Model code/Part number:	920B / 7R0115-7021A	Customer: TRMX	-		WI-ENG-PDE-65	55C	
				☐ PROTOTYPE	PRE-LAUNCH	Car Model: TOYOTA-TACOMA MASSPRO	Revision No.:	0	Page No.:	
			Purpose:	☐ PROTOTYPE	☐ PRE-LAUNCH	MASSPRO	Revision No	0	Page No	1 of 5
PARTS:		1. Assy	parts; Black tape		JIG:	n/a				
N	0.	Р	ROCESS NAME	WORK F	TOOLS/PPE	(QUALITY POINTERS			
					Table Lay-out		Safety Instruction Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.)			
1		P3	Table lay-out	Assy parts	Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.	1. No missii	No missing parts/tools No excess parts/tools			
					Alert level For any trouble, inform the Assembly Assistan Supervisor or Line Leader for immediate corrective action.	t				
				puroprofer of						
<u> </u>				Revision History			Prepared by	Reviewed by	Approved by	Noted by
							$ \sim$ \sim			
10/09/24		Initial issu	ue. Separate Y-taping process fro	om P2.		D.Castillo C.Villanuev A. Arañes r	n/a Castillo	C. Villanueva	A. Arañes	n/a
Eff. Date	Rev. No			Details of Change	Revised Reviewed Approved No	oted Est. Date: Oc	tober 09, 2024			








			Effectivity Date:	October 09, 2024							
		Process Name/Title:	TAPING ASSEMBLY PROCESS					Validity Date:	n/a		
		Model code/Part number:	920B / 7R0115-7021A		Customer:	TRMX	Car Model: TOYOTA-TACOMA	Document No.:		WI-ENG-PDE-6	55C
		Purpose:	☐ PROTOTYPE		PRE-LAUNCH		MASSPRO	Revision No.:	0	Page No.:	5 of 5
PARTS:	1. Assy	Assy parts						JIG:	n/a		

VISUAL INSPECTION/ QUALITY CHECKPOINTS

TAPING - P3

7R0115-7021A



1

No Wrong orientation of Connector with clip clamp

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.