
				WORK INS	Effectivity Date:	te: February 06, 20		4			
K)			Process Name/Title:		IP ASSEMBLY PROC		Validity Date:				
			Model code/Part number:	930B / 7N0202-7020A	Customer: TRJ	Car Model: TOYOTA 4RUNNE	Document No.:		WI-ENG-PDE-82	24	
			Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	1 of 6	
PARTS:		3. Clam	p 82711-33650 (B) p 82711-48210 (B)		4. Clamp 82711-52090 5. Brown tape 6. Black tape [3 pcs.]		JIG:	1. Assembl			
NO. PROCESS NAME		ROCESS NAME	WORK I	TOOLS/PPE	C	QUALITY POINT	TERS				
	3. Clamp 82711-48210 (B) 6. Black tape [3 pcs.]										
-				Revision History			Prepared by R	Reviewed by	Approved by	Noted by	
02/06/24	0	Initial issu				A.Hemandez C.Villanueva A. Arañes	Ohmonder	long Hours	-		
		miliai iSSL	ıc.	Dataile of Observe				.Villanueva	_/ A.(Arailles	n/a	
Eff. Date	Rev. No			Details of Change		Revised Reviewed Approved	Noted Est. Date: Febru	uary 06, 2024			



			WORK INS	STRUCTION		Effectivity Date:		February 06, 20	)24
		Process Name/Title:	CLAM	Validity Date:	Validity Date: n/a				
		Model code/Part number:	930B / 7N0202-7020A	Customer: TRJ	Car Model: TOYOTA 4RUNN	ER Document No.:		WI-ENG-PDE-8	824
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	3 of 6
PARTS:	1. Assy	parts				JIG:	1. Assemb	oly jig	
NO.	P	ROCESS NAME	WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	(	QUALITY POIN	ITERS
3	P2	Clamp Assembly	STOPPER SETTING  1. Get the assy part and set to jig. (See setting). First, set the connector 6189-and lock. Continue to set the harness ir with PCB end together within stopper the check also the clamp location 1 seque abnormality, STOP and immediately C WAIT for further instruction then continuated the tape using both hands. Press the Continue if sequence on clamp location.	e above picture for the correct-0451 (W) to Receiver base in jig. Last, set B/W-G wires then press by toggle clamp.  and CLAMP ON was ON.  and Clamp on was on.  and clamp on the leader the attention of the leader the process.	4. Hold the tape on clamp low windings of tape then cut the Press the SW button after ta clamp location 4 was ON.  5. Hold the tape on clamp location 4 was ON.	e tape using both hands.  bing. Continue if sequence on  cation 1, make 3 windings of  both hands. Press the SW  d will be heard.	1. Pleas start of wrong L  1. No wror 2. No wror 3. No dam	e check the clamp clamp assembly use of clamp.  Ing use of parts and use of tape aged clamp aged aged aged aged aged aged aged aged	ap first before to avoid



WORK INSTRUCTION Effectivity Date: February 06, 2024									
		Process Name/Title:	CLAMP ASSEMBLY PROCESS Validity Date:				n/a		
		Model code/Part number:	930B / 7N0202-7020A	Customer: TRJ	Car Model: TOYOTA 4RUNNER	Document No.:		WI-ENG-PDE-8	324
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	5 of 6
PARTS:	1. Assy parts					JIG:	n/a		
NO.	PROCESS NAME		WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	QUALITY POINTERS		
5	P2	Measurement	102±5mm  0-5mm  MEASURING TAPE  6 7 8 9 1 2 3 4 5 6 7 8 9	220±3mm	Note: Measurement from end of clamp tapir (82711-33650) to end of PCB.	£3mm	Importa  1. Pleas measur measur 2. For H  Docum  1. Refer assemb	nt reminders/Not e use calibrated/ ing tape when ge ement. latsumono and O ent reference/s: r to WI-PRO-ASY- oly Hatsomono, Nearimono Inspect	verified tting the warimono.  -056 for Sub lakamono,



		A	WORK INSTRUCTION				Effectivity Date:	February 06, 2024			
			Process Name/Title:	CLAM	Validity Date:	n/a					
			Model code/Part number:	930B / 7N0202-7020A	Customer: TRJ	Car Model: TOYOTA 4RUNNER	Document No.:		WI-ENG-PDE-8	24	
			Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	6 of 6	
	PARTS:	n/a					JIG:	n/a			
, 1								l			


## QUALITY CHECKPOINTS

## 0202-7020A



GOOD





## **NO GOOD**

1 No WRONG INSERT No UNLOCKED/HALFLOCKED **NO TBO** 

**NO Missing Clamp** No Wrong color of tape (Brown)

3) No Wrong color of tape (Black)

**NO GOOD** 

4) No Missing Tape

No DEFORMED **ERMINAL/PCB** 

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.