


			WORK INSTRUCTION Effectivity							April 02, 2025		
JB			Process Name/Title:	SUB-ASSEMBLY CONTINUIT		OYOTA RAV-4	Valid	ity Date:		n/a		
			Model code/Part number:	311D/400D 17L991-7111 Customer: TRMX	Docu	Document No.:		WI-ENG-PDE-1228				
			Purpose:	☐ PROTOTYPE ☐ PRE-LAUNCH	MASSPRO		Revis	sion No.:	0	Page No.:	1 of 7	
PARTS:		n/a								Nacman Machine     Continuity Test     Controller		
NO	Ο.	Р	ROCESS NAME	WORK PROCEDURE/ ILLUSTRATION						QUALITY POIN	ITERS	
1	1 Continuity Test Table Lay-out Continuity Test Table Lay-out							afety Instruction Be sure to wear orescribed personate transport of the sure to wear orescribed personate transport of the sure of the sur	al ent s,	ng parts/tools s parts/tools		
	i.	•		Revision History			,	Prepared by	Checked by	Reviewed by	Approved by	
04/02/25 Eff. Date	0			Initial issue.	A.Hernandez J.Loten		A.Arañes	Okimow diy A.Hernandez	J.Loterte	C.Villanueva	A Araños	
Lii. Date	Kev. No	<u> </u>		Details of Change	Revised Check	ed Reviewed	Approved	Est. Date:	April 2, 2025			

			WORK	INSTRUCTION	Effectivity Date:	April 02, 2025		
		Process Name/Title:	SUB-	ASSEMBLY CONTINUIT	Validity Date:	n/a		
		Model code/Part number:	311D/400D 17L991-7111 Customer: TRMX Car Model: TOYOTA RAV-4 TOYOTA Bz4x (BEV)		Document No.:	WI-ENG-PDE-1228		
		Purpose:	☐ PROTOTYPE	PRE-LAUNCH	■ MASSPRO	Revision No.:	0 Page No.:	2 of 7
PARTS:	n/a					JIG:		
NO.	PROCESS NAME		WOI	RK PROCEDURE/ ILLUSTR	TOOLS/PPE	QUALITY POINTERS		
2	Continuity Test	Machine Set-up	2. Connect the inspection to the inspection jig, then A to A then B to B	bac Plus	Connect the power cord to the power k of the main unit.  g the power cord plug into the power and the power cord plug into the power and the power and the inspection jig) attached	outlet.	Make sure that the power switch main unit is set to "OFF".     Before connecting cables and jiturn off the power of the main unit.	gs. please





WORK INSTRUCTION Effectivity Date:									April 02, 2025		
		Process Name/Title:		SEMBLY CONTINUIT	Y TEST		Validity Date:	n/a			
		Model code/Part number:	311D/400D 17L991-7111	Customer: TRMX	Car Model:	TOYOTA RAV-4 TOYOTA Bz4x (BEV)	Document No.:		WI-ENG-PDE-12	228	
		Purpose:	PROTOTYPE	☐ PRE-LAUNCH	■ MASSPRO		Revision No.:	0	Page No.:	5 of 7	
PARTS:	1. Assy Parts						JIG:	1. Continuit	1. Continuity test		
NO.	PF	ROCESS NAME	WORK PROCEDURE/ ILLUSTRATION				TOOLS/PPE	(	QUALITY POIN	TERS	
4	Continuity Test	Wire harness testing	1. Insert the connector (4A1820-0000 connector receiver base 1	(W)) to 2. In	assert the connectinector receiver by		R 7	nperation Refer to F- 1. No wron 2. No dam. 3. Hold onl	quipment inspection PDE-010A-B  The setting of couple age or broken confliction on coupler during the samp of the	er nector pin g insertion	




		WORK INSTRUCTION E						Effectivity Date:	April 02, 2025			
		Process Name/Title:	SUB-ASSEMBLY CONTINUITY TEST					Validity Date:	n/a			
		Model code/Part number:	311D/400D 17L991-7111	Customer:	TRMX	Car Model:	TOYOTA RAV-4 TOYOTA Bz4x (BEV)	Document No.:		WI-ENG-PDE-1	228	
		Purpose:	☐ PROTOTYPE	PRE-LAUNC	4	■ MASSPRO	)	Revision No.:	0	Page No.:	7 of 7	
PARTS:	n/a							JIG:	n/a			

## **VISUAL INSPECTION/ QUALITY CHECKPOINTS**

## **CONTINUITY TEST**

## 17L991-7111



- 1 No Missing Punch Mark
- **No Missing Tesa Taping**
- 3 No Peel-off Tape

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.