

Process Name/ Title:

CONTACT SWITCH ASSEMBLY/

Parts usage important precautions

Document No:

WI-PRO-COS-019

WORK INSTRUCTION

Effective Date:

August 15, 2018

Product Code/Name: ALL

Customer Code: TRJ / TRQSS

Rev. No.:

Page No.:

Page 1 of 2

Work Procedure/ Illustration

Records/Remarks/ **Quality Pointers**

1. Rosin solder important precautions



(1) items name inspections

2 wire diameter • flux number inspections



③ usage deadline inspection Val.2010.07

検査2

2. SUB-ASSY important usage precautions

1 production day inspection, daily report entry



2009/

9/

090902066

production lot

7K0250-7030

terminal conductor deadline usage, production day, within or less than 6months

3. stator important usage precaution

1 items number inspections 7K0575-0022 7K0639-0021

2 production day inspection, daily entry

2/



stator dead line usage, production day, within or less than 6months

annotation: please do not use wrong item, expired item

if there is wrong or expired item report it to supervision staff

						Prepare	Check	Approve
August 15, 2018	À	Adjustment on declaration of recorded lot number on stator and revision of storage for solder wire	L. Alarzar		O. Merin	Comp.	A-1	There
- 1	NA	Previously revised Work Instruction from NBC Shanghai and establishment of translationNBHS-1597 (for history purpose only)	L. Suarez		T. Sugiyama	LAlarzar	M. Demiden	O Nierin
Eff./Rev. Date	Rev. No.	Details of change	Prepare	Check	Approve	Est. date:	06/01	2017

1



Process Name/ Title:

CONTACT SWITCH ASSEMBLY/

Parts usage important precautions

Document No:

WI-PRO-COS-019

WORK INSTRUCTION

Effective Date:

August 15, 2018

Product Code/Name:

Customer Code: TRJ

Rev. No.:

Page No.:

Page 2 of 2

Work Procedure/ Illustration

Records/Remarks/ Quality Pointers


1. rosin solder replacement procedure



1 items name inspections

€C⊕ SOLDER RMA02

② wire diameter • flux number inspections



3 usage deadline inspection



when you are going to replace rosin solder (check) 1 items name 2 wire diameter • flux number inspection items validation usage(expiration) 3 always get at the front end part of wire shooter rack_o



Minimum Capacity - 8 rolls Maximum Capacity - 12 rolls

2. stator replacement procedure

1 items number inspections



2 production day inspection, daily entry





when you are going to replace the stator check production lot# place the old one in front, and the new one place it in the back side

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited. MBC (Philippines)
MASTER COPY