

After getting the stator pack for issue to line, put the "first out" label to the next box (ex: from box 4

no. 1 to box no. 2).



## 3 HOLES: 7K0639-0021 /

WITH DOT: 7M0011-0020 STATOR

Put received stator pack to storage box. Attach label "first out" to first stator received and "last in" to last stator received.

There must be label attached "old lot" for lot ongoing use in line or first lot number received and "new lot" for last received stator lot for proper identification.



## 3HOLES (7K0630/0021):


Max. 3 aluminum pack per division.

## WITH DOT (7M0011-0020):

Max. 2 aluminum pack per division

-										
	Nov. 17, 2023	/ <u>5</u> \	General revision of procedure		L.Famodulan	A.Ayop	O.Merin	Prepare	Check	Approve
	June 1, 2022	4	Removal of clip tag and visual board change into white container and parts data labe		M.Marquez	C.Lalican	O.Merin	۸ ۱		(/
	July 13, 2021	3		Revise rule of stator expiration.	A.Ayop	D.Cornero	O.Merin	Alaha	and	14
	Apr. 26, 2019	019 2 ID tag and visual board inclu		ID tag and visual board inclusion for proper visualization.	M. Demiden	O. Merin	O. Merin	L.Famodulan	CA.Ayøp	O Merin
	Eff. Date	te Rev.		Details of change	Revise	Check	Approve	Est. date:	05/27	/2017

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or nisappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited. **NBC** (Philippines) **MASTER COPY** 



		ALL			Rev. No.:	Rev. No.: <b>5</b>		2 of 2
No.	Work Procedure/ Illustration						Records/Remarks/ Quality Pointers	
2	to box no. 6). Car scissor. Fill out of	starting from box no. 1 (up refully open the pack using data parts and attached to eack for issue in line.			3D711	CLOT OF ATOR MAGNETIC		
3	line, put the "fir partition (ex: fi	e stator pack for issue to rst out" label to the next rom 1st partition to the xt partition).		Section 1				
C. STATOR LINE ISSUANCE								
1	proper sequen	storage box following the ce of boxes and FIFO of nen issue to line.	Lot numbe	PART NUMBER   1   7K0575-002	22H		label must	nat parts data be the same pack label.
2		of stator to line, put the el in designated location in line.		TM6527-70201				
3	Mesh basket  Note: Ensure clean. Empty v kept for 3 d	ock and pour it into the t slowly and carefully.  e that mesh basket is vaccuum pack must be ays until all stator is onsumed.	CTATOR				Dropped sta as "NG" a	opped stator. ator considered nd endorse to mmediately.
PROPI	EK STORING C	OF LOOSE / EXCESS	SIATOR	11 20				
	■ Return to vacc parts label.	and long holiday cuum pack with loose nside the vaccuum age box.		LINI STATOR LOOSE PARTS IN 30117030				the data label n designated
	gel. ■ Put inside the	cuum pack with sillica container in line. d upon resumption of lie						identification tch the actual the box.

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY