

No.

AII

Work Procedure/ Illustration


Records/Remarks/ Quality Pointers

1 of 3



ΑII





Get the vaccum cleaner then vaccum the soldering machine, shooter and ESD mat to clean out excess solder and dust.

Important Notice:

Page No.:

- Ensure that soldering body is turned-off during cleaning
- 2. Ensure to wear gloves while cleaning
- the soldering machine
 3. Do not move the
 magnifying glass while
 brushing the soldering
 jig for eye protection
 4. Use Googles during
 cleaning of jig or
 machine













Rev. No.:


Holding the product while cleaning is prohibited.

| G

2

3

Get cleaning wire holder, open the cover and disposed solder waste in the proper disposal. Return to its position.





Frequency of cleaning

Every day after breaktime (short /long), clean the area so it is free from wire strands in the working area.



NO GOOD

Change the cleaning wire holder immediately if it is already deformed or worn-out to avoid damage to the soldering tip or stick.

Check wire cleaning condition , immediately change cleaning wire if it is already have detached wire scrap , worn-out and hardened.

Note: Check the wire cleaner reference at your soldering area.





Make sure that all flux was removed to prevent probe pin from stuck up.
Do not use bamboo stick to remove the flux on soldering jig to avoid broken probe pin.


For hotmelt soldering Clean the probe pin and soldering jig with flux remover then, clean again with alcohol to remove the remaining flux remover. For **Contact Switch** use alcohol only.

09/11/2024	6	Include proper cleaning of probe pin	L.Salonga	A. Ayop	W.Carbillon	Prepared	Checked	Approved
06/03/2024	5	Include proper use of googles during cleaning of soldering machines	L. Famodulan	A. Ayop	W.Carbillon			
02/21/2024	4	Revise procedure on cleaning soldering jig and probe pin.	A.Ayop	C.Calayan	W.Carbillon			
01/23/2024	3	Revise procedure on cleaning soldering jig and probe pin.	A.Ayop	C.Calayan	W.Carbillon			
08/01/2023	2	General revision	L. Famodulan	W. Cabillon	O. Merin			
07/04/2022	1	Cleaning of Soldering jig prior production after breaktime	L. Famodulan	C. Luna	O. Merin	d di	anna	Salson
05/07/2022	0	Merge Work Instruction of WI-PRO-C0S-053 and WI-PRO-SHM-033 into common procedure	C. Lalican	O. Merin	O. Merin	L. Famodulan	A. Ayop	W.Carbillon
Eff./Rev. Date	Rev. No.	Details of change	Revise	Check	Approve	Est. date:	May 07	, 2022

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY



Soldering Machine Cleaning

Document No:

WI-PRO-COM-019

WORK INSTRUCTION Product Code/Name: ΑII

Customer Code: ΑII

Effective Date: Rev. No.:

September 11, 2024 Page No.:

1 of 3

No.

Work Procedure/ Illustration

Records/Remarks/ **Quality Pointers**





Frequency of cleaning

Every day after breaktime (short /long) prior production.

Jig must free from dust foreign etc.

When encountering rust or waste during running , immediately clean the jig Note: Use googles

When soldering brush tip looks like below picture immediately change it.



NO GOOD

Holding the product while cleaning is prohibited.

For **CSW**, use "Alcohol" for cleaning, **Do NOT** use "Flux remover" to avoid discoloration.

5




Frequency of cleaning

Clean the rack after finishing it with hot melt prior to soldering to avoid foreign object in the PCB

Holding the product while cleaning is prohibited.

Hotmelt soldering rack, use soldering brush.

6





Using wipes clean the soldering machine cover inside and out, wipe the soldering body and soldering iron holder.

7



Clean working table and mesh wire table it will free from foreign objects.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines) **MASTER COPY**



Process Name/ Title:						
Soldering Mach	Document N	lo:	WI-PRO-COM-019			
WORK INSTE	Effective Da	ite:	September 11, 2024			
Product Code/Name:	Customer Code:	D 11		- ·	4.10	

All

DO'S and DON'T

DO'S



Use a vacuum when clean rights for illineinhes to avoid a MASTER COPY

All

DONT'S




Rev. No.:


Avoid blowing when cleaning the jig to avoid dust and dirt hitting the eyes.

Page No.:

1 of 3



Keep your goggles on when cleaning the jigs or machine.



Googles is strictly implemented during the cleaning of machines and jigs.





Use cotton buds with flux remover to remove the flux on soldering jig.





Do not use bamboo stick to remove the flux on soldering jig.





Avoid chatting during cleaning.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY