

Process Name/ Title:

CONTACT SWITCH ASSEMBLY/ Soldering operation Health and Safety

WORK INSTRUCTION

Customer Code:

WI-PRO-COS-031

Effective Date:

March 16, 2018

Product Code/Name:

Rev No

Document No:

Page No :

		ALL	TRJ	INEV. NO	1	raye	NO	Page 1 of 1		
No.	Work Procedure/ Illustration							Records/Remarks/ Quality Pointers		
	1. operations right operations right operations right operations right operations right operations always wear years always turn to ventilation.									
		do not leave flux, soldering iron								
						1		1		

2. environmental aspect features

① caution: be careful because clothes is contaminated with the hazardous substance (inside the soldering is attach with lead, flux etc.) (3S arrangement orderlines cleaning implementations)

6 be careful always with the electric shock and burn, (do not touch the soldering tip, check the electric cord)

- 2 after operation always wash your hands (implementations),
- 3 always clean the operation place. (soldering powder, garbage(trash) mixing preventions)
- 4 soldering iron wire tangling is very dangerous and strictly prohibited because it may cause of fire.

smoke filter





protective equipment



ESD Facemask





		L ,					Prepare	Check	Approve
03/16/2018	2018-L3-WI-021	Λ	Replace safety goggles to facemask as PPE for Soldering.		M. Demiden		11	A	
06/01/2017	2017-L3-WI-057	0	Established ISO format. Initial issue	M. Vasallo		T. Sugiyama	SAM	Dermije	- N/
-	NBHS-1644	-	Previously established work instruction from NBS Shanghai (for history purpose only)	Takenaka		Herose	L. Alarzar	M. Demiden	O. Merin
Eff./Rev. Date	Doc/DRCN No.	Rev. No.(if applicable)	Details of change	Revise	Check	Approve	Est. date:	06/01	/2017