			WORK INSTRUCTION	Effectivity Date:	April 17, 2021				
		Process Name/Title:	TAPING ASSEMBLY	Validity Date:	n/a				
		Product Name/Code:	100B / 7M0593-7020B Customer:	TRJ	Document No.:	WI-ENG-PDE-154C			
		Purpose:	PROTOTYPE PRE-LAUNCH	MASSPRO	Revision No.:	3 Page No.: 1 of 6			
PARTS:	1. Assy 2. Black				JIG:	n/a			
NO.	Р	ROCESS NAME	WORK PROCEDURE/ ILI	LUSTRATION	TOOLS/PPE	QUALITY POINTERS			
1	P3	1. Hold the corrugated tube using left hand and begin taping using right hand. 2. Make 1/2 shift corrugated tube.		1/2 shifting Repeat the process until the end of a tube. Make 3 winds and then cut the tape.	Safety Instruction Be sure to wear required personal protective equipment during operation (gloves, finger cots, etc.) Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in	1. No peel-off tape 2. No flip out tape 3. No loose tape 4. No wrong use of tape 5. No exposed COT NOTE: USE WHITE TAPE FOR EASY VISUALIZATION OF SHIFTING LINES, BUT ACTUAL SHOULD BE BLACK TAPE.			
			Revision History			eviewed by Approved by Noted by			
04/17/21 3		me improvements. Put assy p			Arañes Minsutay	1) th (0-1) (m/)			
09/30/20 2 04/10/18 0		d effectivity and validity date. It is stablished as Engineering			araries /	Vilianueva A. Shimamura A. Aranes			
Eff. Date Rev. No		., coabilotica as Enginoening	Details of Change			0, 2018			

				WORK INSTRUC	CTION		Effectivity Date:		April 17	, 2021			
		Process Name/Title:		TAPING ASS	SEMBLY PROCE	ESS	Validity Date:		n/a	a			
		Product Name/Code:	100B /	7M0593-7020B	Customer:	TRJ	Document No.:		WI-ENG-PDE-154C				
		Purpose:	☐ PROTOTYPE		PRE-LAUNCH	MASSPRO	Revision No.:		3 Page No.:	2 of 6			
	1								ı				
PARTS:	1. Assy 2. Black	parts tape						JIG	1. T-Taping jig				
NO.	PI	ROCESS NAME		WORK PROCE	DURE/ ILLUSTRA	TION	TOOLS/P	PE	QUALITY POINTERS				
2	P3	T-taping		ø7 L=163±3 ø5 L=201±3mm ø5 L=410±4mm	prrugated tube to form inv	tation of n cut the tape. Ø7 L=96±3mm	T-TAPING J	3110,506	1. No flip out tape 2. No tape peeling 3. No loose tape 4. No wrong use of ta	аре			

WORK INSTRUCTION												
					WORK INSTRUC		Effectivity Date:		April 17, 2021			
		Process Name/Title:			TAPING ASS	EMBLY PRO	Validity Date:		n/a			
	5	Product Name/Code:	100B	1	7M0593-7020B	Customer:	TRJ	Document No.:			WI-ENG-P	DE-154C
		Purpose:	☐ F	PROTOTYP	E	PRE-LAUNCH	MASSPRO	Revision No.:		3	Page No.:	3 of 6
								I .			<u>'</u>	
PARTS:	1. Assy 2. Black	parts tape							JIG	1. T-Tap	ing jig	
NO.	PF	ROCESS NAME			WORK PROCE	DURE/ ILLUST	RATION	TOOLS/	PPE	QUALITY POINTERS		
2	P3	T-taping (Continuation)	corrugate	d tubes us	e middle to fix the 4 sing right hand.	4. Wind the side	e tape from front to back at the right	T-TAPING		1. No flip 2. No tap 3. No loc 4. No wro	VISUALIZAT FING LINES, JLD BE BLAC o out tape be peeling	BUT ACTUAL K TAPE.

				Effectivity Date:	April 17, 2021				
		Process Name/Title:		TAPING ASS	EMBLY PROCE	ESS	Validity Date:	n/a	
		Product Name/Code:	100B /	7M0593-7020B	Customer:	TRJ	Document No.:	WI-ENG-PDE-154C	
		Purpose:	☐ PROTOTYPE		PRE-LAUNCH	MASSPRO	Revision No.:	3 Page No.: 4 of 6	
PARTS:	1. Assy	y parts k tape					JIG	1. T-Taping jig	
NO.	F	PROCESS NAME		WORK PROCED	URE/ ILLUSTRA	TION	TOOLS/PPE	QUALITY POINTERS	
2	P3	T-taping (Continuation)			the tape from back to oss pattern) 10. From 2/3 shift	(19mm)	n/a	NOTE: USE YELLOW TAPE FOR EASY VISUALIZATION OF SHIFTING LINES, BUT ACTUAL SHOULD BE BLACK TAPE. 1. No flip out tape 2. No tape peeling 3. No loose tape 4. No wrong use of tape 5. No wrong dimension	

			WORK INSTRUCTION							Effec	Effectivity Date:			April 17, 2021			
	Process Name/Title:		TAPING ASSEMBLY PROCESS							Validi	Validity Date:			n/a			
		Product Name/Code:	100B	1	7M0593-702	20B	Customer:		TRJ	Docu	ment No.:			WI-ENG-P	DE-154C		
		Purpose:	☐ PF	ROTOTYP	E		PRE-LAUNCH		MASSPRO	Revis	ion No.:		3	Page No.:	5 of 6		
										<u> </u>		1	1				
	1. Assy 2. Black											JIG	n/a				
NO.	PI	ROCESS NAME			WORK PF	OCE	OURE/ ILLU	STRATION			TOOLS/	PPE	C	QUALITY POINTERS			
2	P3	T-taping (Continuation)	L 13. From	attern)	m front to back R R side, wind the tape to center	L	uidth must be sa	me as tape (19r	tube (3 winds), nm) R ng to front side		n/a		1. No fli 2. No ta 3. No lo 4. No w	Y VISUALIZAT	BUT ACTUAL CK TAPE.		

					WORK INSTRUC	Effectivity Date:		April 17, 2021					
		Process Name/Title:			TAPING ASS			Validity Date:		n/a			
	7	Product Name/Code:	100B	1	7M0593-7020B	Customer:	TRJ	Document No.:			WI-ENG-P	DE-154C	
		Purpose:	☐ P	ROTOTYP		PRE-LAUNCH	MASSPRO	Revision No.:		3	Page No.:	6 of 6	
PARTS:	1. Assy 2. Black	parts tape							JIG	n/a			
NO.	PI	ROCESS NAME			WORK PROCED	URE/ ILLUSTF	RATION	TOOLS/P	PE	QUALITY POINTERS			
2	P3	T-taping (Continuation)	pattern)		Taping Condition 19mm 19mm	width must be	ght side corrugated tube (3 winds), same as tape (19mm) r taping, check the ement and condition of tape.	MEASURING 6 7 8 9 10 1 2 3 4 5	TAPE	1. No flij 2. No ta 3. No lo 4. No wi 5. No wi	P Out tape pe out tape pe peeling ose tape rong use of ta rong dimensi	ape on arted/verified when getting	