

	Process Name/ Title:	rocess Name/ Title:						
١	Pb-Free Solder Wire S	Document No:		WI-PRO-COS-047 November 3, 2023				
7	WORK INST	Effective Date:						
	Product Code/Name:	Customer Code:	Rev. No.:	2	Page No.:	1 of 1		
	A11	ALI	Rev. No	4	rage No	1 01 1		

Records/Remarks/ Work Procedure/ Illustration No. **Quality Pointers**


ALL

1. Solder wire FIFO is based on chute type system to strictly implement First In-First Out and is easy to use.



ALL

- 2. Storage capacity is MAX: 12 rolls and MIN: 8 rolls.
- * In case Storage Capacity reached Minimum Stocks, request immediately (4 rolls). (Do not overstock)
- * Check the specification of solder wire before receiving, to prevent misuse of wrong solder wire. (Figure 1)
- * Do not use solder wire with different specification. In case of wrong wire supplied, inform immediate superior.



* always lock the chute after use.



3. For usage, bring the tag of the line that needs for new supply. Compare the actual item to the picture on the tag. And lastly, encode the date of change and expiration date



Figure 1 Solder Wire Specification

Figure 3 Comparison of Tag



Figure 4 Exchange date and expiration

4. Update Pb-Free Solder Wire Expiration Checksheet (F-PRO-COS-011) and Soldering Iron Temperature Daily Checksheet (F-PRO-COS-010) for daily checking.





F-PRO-COS-011



F-PRO-COS-010

							Prepare	Check	Approve
							A 1		
	11/3/2023	/2	Added checkpoint no. 4 in solder wire specification and update item no. 3 and 4 pictures.	L.Famodulan	A.Ayop	W.Carbillon	Ah-Adin	and	Call.
	9/9/2019	1	Change Customer Code from TRJ/TRQSS to ALL	J. Lorzano	D. Cornero		L.Famodulan	A.Ay66	W.¢arbillon
	Eff./Rev. Date	ff./Rev. Date Rev. No. Details of change		Revise	Check	Approve	Est. date:	1/6/2018	