 Process Name/ Title:						
STOP, CALL AND W	AIT PROCEDURE	Document No	o:	WI-WHS-RMW-010		
WORK INSTRUCTION		Effective Date:		March 13, 2025		
Product Code/Name:	Customer Code:	Rev. No.:	2	Page No.:	1 of 3	
n/a	n/a	Rev. No	3	rage No	1 01 3	

Work Procedure/ Illustration No. STOP, CALL AND WAIT PROCEDURE DEPARTMENT / SECTION : WAREHOUSE / RM ABNORMALITY 15-20 mins. 20 mins. or more 0 - 5 mins 5 - 10 mins INFORMATION FLOW PLANT MANAGER/DIRECTOR GEN **ABNORMALITY TEAM MEMBERS** LEADER **SUPERVISOR** SECTION MANAGER MANAGER Damaged STOP the process Instruct members not to use the Check the condition of the Verify the problem and Verify the problem and quipments/Tools CALL the attention of Leader. Do not ent/tools ction taken action taken ontinue the process Instruct to separate the eq IF CAN DEAL FIXING THE EQUIPMENT put label using Management Tag WAIT for the instruction of the leader Instruct member to proceed for the superior and observe Standard Waiting Inform immediate Superior epair of the equip IF CANNOT DEAL FIXING THE EQUIPMENT 1 Request to Engineering/ Maintenance Team for the assesment/repair of the affected equipment/tools Material Overflow STOP the process. Monitor the delivery timing of the Inform immediate Superior Verify the problem and CALL the attention of Leader. Do not Coordinate to Purchasing Team by affected material(s) continue the process. sending list of Over stock materials via > Coordinate to Purchasing team for WAIT for the instruction of the leader 2 superior and observe Standard Waiting > Instruct members to store oosition over stock materials at Overflow Critical Stock level STOP the process. Inform immediate Superior Inform production team for the Verify the problem and CALL the attention of Leader. Do not Coordinate to Purchasing Team by status of delivery of materials > Monitor the actual delivery of continue the process. ending list of critical materials via MATERIA WAIT for the instruction of the leader 3 superior and observe Standard Waiting > Ask Purchasing team for the delivery Coordinate to Purchasing team for schedule of the affected materials he countermeasures nventory Variance STOP the process. Inform immediate Superior Create countermesures to avoid Verify the problem and CALL the attention of Leader. Do not Gather data needed Actual vs Monitoring) continue the process. Check system transaction history of > Report to Department Manager for WAIT for the instruction of the leader he approval of any inventory ncoming and Issuance 4 superior and observe Standard Waiting > Conduct inventory count of the affected djustment needed materials Analyze the root cause of the variance STOP the process Check the condition of the Dehumidifier Coordinate and ask to Engineering Verify the problem and ountered below ALL the attention of Leader. Do not hygrometer if it is functioning Feam for possible cause and effect on minimum or above ontinue the process > Inform immediate Superior the fluctuation of Thermohygrometer maximum Temperature WAIT for the instruction of the leader reading 5 nd Humidity Reading uperior and observe Standard Waiting Coordinate to QA/QC Team for the ğ osition re-inspection of the Terminal raw Materials Dropped STOP the process Inform immediate Superior Prepare incident report Verify the problem and Verify the problem and CALL the attention of Leader. Do not Instruct members to Hold the materials at Parts Request to QA/QC team for the rection taken ontinue the process. he temporary WH Holding area nspection and proper identification o WAIT for the instruction of the leader > Record the incident to the Dropped Parts the materials and wait for the superior and observe Standard Waiting completion of the inspection > If OK to use, endorse to member for proper storage > If Not OK (NG), request to QA/QC 6 team for inspection resul Instruct leader to attached Defect > Instruct leader for the preparation of disposal form > Provide countermeasure to avoid Prepared by: Approved by: E.Sanche N.Kitamu Revised procedure on Item no.9 Receiving of items: With Damaged/Collapesed/Wet shipment 04/26/2 M.Banab N.Kitamu I.Aranas 02/17/24 M.Banaba I.Aranas N.Kitamura 200 atome of 04/26/23 0 Initial Issue E.Sanchez M.Banabar N.Kitamura Details of change Approve Est. date: April 26, 2023

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY

	Process Name/ Title:						
	STOP, CALL AND WA	AIT PROCEDURE	Document N	0:	WI-WHS-RMW-010		
	WORK INSTR	UCTION	Effective Dat	e:	March 1	13, 2025	
	Product Code/Name:	Customer Code:	Rev. No.:	2	Page No.:	2 of 3	
	n/a	n/a	Rev. No	3	rage No	2013	

No.	. Work Procedure/ Illustration							
	STOP, CALL AND WAIT PROCEDURE							
		EPARTMENT / SECTION NORMALITY INFORMATION FLOW	N: WAREHOUSE / FINISHED GO	5 - 10 mins.	10 - 15 mins.	15-20 mins.	20 mins. or more	
		ABNORMALITY	TEAM MEMBERS	LEADER	SUPERVISOR	SECTION MANAGER	PLANT MANAGER/DIRECTOR GEN. MANAGER	
AATERIAL			STOP the process. CALL the attention of Leader. Do not continue the process. WAIT for the instruction of the leader superior and observe Standard Waiting Position	> Received an information from WH members, Abnormality/Quality Team > Hold the materials in WH Temporary Holding Area > Inform immediate Superior	> Report to Department Manager > Instruct Leader to check the affected materials lot no. and quantity > Check the materials inventory stock level - Inf OK Stock level - Inform the quantity of the affected materials to concerned Department - If in Critical stocks - Inform Purchasing team to request additional order from supplier > Wait for the final disposition from Quality Team - If OK - instruct leader to return the materials in its proper location - If NG - Instruct leader to prepare the materials for transmittal to Quality Team for proper Holding		> Verify the problem and action taken	
α MATERIAL			- If the incident occurs before receiving the items from supplier, Do not receive the items - If the incident occurs at the wh storage area, Hold the materials in WH Holding area STOP the process. CALL the attention of Leader. Do not continue WAIT for the instruction of the leader superior and observe Standard Waiting Position	> Check the affected materials > Determine the cause of expired materials > Inform immediate Superior	> Report to Department Manager > Coordinate to Quality Team for the disposition of expired materials > If Ok to use - Instruct leader to apply 4m change for the affected materials for traceability purposes > If NG - Instruct leader to endorse the affected materials to Quality team for proper Holding and disposition > Provide countermeasure to prevent expired materials	> Verify the problem and action taken	None	
ئ MATERIAL	Qu	ımaged / Collapsed / et shipment	STOP the process. CALL the attention of Leader. Do not continue the process WAIT for the instruction of the Leader/Superior and observe Standard Waiting Position	> Check the report of members > Inspect the materials and take photos as evidence If Imported or Overseas Delivery: > Ask forwarder/Courier for the damaged report > Inform immediate Superior > Check the report of members > Inform immediate Superior	> Verify the report > Inform Purchasing team and Section Manager > Wait for Purchasing advise > If Purchasing advise not to receive the materials > Instruct leader/members not to receive the materials > If Purchasing advise is to proceed with the receiving of materials > Instruct members to received the materials and transfer the affected materials to WH Temporary Holding area > Inform QA team for witnessing and verification on the affected damaged delivery within the day > Create a report and send an email notification to QA Team for the creation of Trouble Report for issuance to Supplier/Forwarder > Wait for QA team disposition > Instruct Leader/members to endorsed affected materials to QA team for proper holding > Verify the report > Inform Purchasing team and Section Manager > Wait for the instruction of Purchasing Team	> Verify the problem and action taken	None	

			rocess Name/ Title:					
		C	STOP, CALL AND WA	AIT PROCEDURE	Document N	0:	WI-WHS-RMW-010	
			WORK INSTR	RUCTION	Effective Date:		March 13, 2025	
			Product Code/Name:	Customer Code:	Rev. No.:	2	Page No.:	3 of 3
			n/a	n/a	Rev. No	3	rage No	3 01 3

No. Work Procedure/ Illustration STOP, CALL AND WAIT PROCEDURE DEPARTMENT / SECTION : WAREHOUSE / FINISHED GOODS 0 - 5 mins. 5 - 10 mins 10 - 15 mins 15-20 mins. 20 mins. or more INFORMATION FLOW PLANT MANAGER/DIRECTOR GEN. MANAGER ABNORMALITY **TEAM MEMBERS SUPERVISOR** SECTION MANAGER LEADER Wrong/No Proper Material Label Inform Purchasing team and Section > Inspect the materials and take photos as evidence Manager > Inform immediate Superior If Purchasing advise not to receive the materials eceive the materials > If Purchasing advise is to proceed vith the receiving of materials > Instruct members to received the materials and transfer the affected STOP the process. materials to WH Temporary Holding CALL the attention of Leader. Verify the problem and 9 > Inform QA team for witnessing and tion taken verification on the affected damaged Do not continue the process delivery within the day Wrong Item Delivered WAIT for the instruction of the Leader/Superior and observe Standar notification to QA Team for the creation of Trouble Report for iss Wait for QA team disposition Instruct Leader/members to endorsed affected materials to QA eam for proper holding Check the condition of manpower WHE Personnel/Staff/ TOP the process. Instruct personnel to go to clinic with > Verify the problem and eader not feeling well CALL the attention of Leader. Do not Inform immediate to superior ssistance for the assess ontinue the process Nurse/Doctor on duty WAIT for the instruction of the leade Check the effect in the o superior and observe Standard Waiting Assigned replacement for his/her jo Report to superior immed 10 Check the condition of manpowe WHE Personnel/Staff/ TOP the process. Verify the problem reported Verify the problem and Verify the problem and action eader involved in ALL the attention of Leader. Do not Inform immediate to superior > Report to superior immediately > Bring the involved personnel in the ction taken ccident/incident ontinue the process WAIT for the instruction of the leader superior and observe Standard Waiting Conduct investigation report 11 ¥ occurence Instruct Delivery personnel to return to Inform Purchasing team to remind Verify the problem and Receiving TOP the process No Peza stamp on ALL the attention of Leader. Do not Peza for proper stamping of receiving supplier's for proper stamping of eceiving documents ontinue the process. documents receiving documents prior delivery of elivery Receipt(DR) WAIT for the instruction of the lea Inform immediate to Superior he materials 12 superior and observe Standard Waiting STOP the process > Instruct member to hold the affected > Verify the report of leader > Verify the problem and > Verify the problem and action Create analysis for the rootcause of materials to end-user continue the process > Check the history of the affected the problem WAIT for the instruction of the leader > Provide countermeasure to avoid materials superior and observe Standard Waiting 13 wrong usage of the materials Report to superior immediately > Inform immediate to Superior ocating. STOP the process. Instruct member to check all materials Verify the report of leader > Verify the problem and Verify the problem and action No attached monthly CALL the attention of Leader. Do not without attachment of monthly color Create analysis for the rootcause of color coding on e problem ontinue the process oding with the same received date naterials WAIT for the instruction of the leader > Verify other materials with same re > Provide countermeasure to avoid 14 superior and observe Standard Waiting oosition > Inform immediate to Superior Report to superior immediately

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited. NBC (Philippines)
MASTER COPY