

Process Name/Title: Forklift Batte	ry Charging	Document No:	WI-PLN-WHS-022		
WORK INST	RUCTION	Effective Date:	February 17, 2021		
Product Code/Name:	Customer Code: N/A	Rev.No.: 0	Page No.: 1 of 1		

			ct Code/Name: Common	Customer Code: N/A		Rev.No.:	0 Pa	ge No). :	1 of 1	I
No.									Records/Rem Quality Poin		
1	Charge the batt remaining bars. Charging time 6 Hor it's full the Charging Turns O	(Maximum urs then when g Automaticaly	Battery charging method in	Batteries level		B					
2	Make sure to off t chargin			3							
3	Charge in well ver and open the ho flame	od (No open		WENG!							
4	Check the outle make sure it is w										
5	When the light t means the charg then unplug th	ging is done,		AUTOMATIC CHARGO AND AUTOMATIC CHARGO AUTOMATI	ARGER	7					
	Note: > Connector must be in good condition and must be properly connected to the charger.										
	Battery water level must be levelized always to ensure no corrosion to avoid short circuit when charging. Hydraulic hose must not be tanggled when after charging.										
	> No open flame during charging (Hydrogen gas will occur). If there is an ABNORMALITY!										
	> STOP, CALL AND WAIT > Call the Attention of Immediate Superior to conduct proper investigation/action to ensure the safety of all employees prior proceed to normal operation.										
<u> </u>	I		<u> </u>					F	repare	Check	Approve

Details of change CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines) MASTER COPY J. Perez

Approve Est. date: