

Process Name/ Title:	
Wire Cutting and Crimping	1
Wire Jointing Procedure	

Document No:

Effective Date:

WI-PRO-CNC-018

July 10, 2017

WORK INSTRUCTION
Product Code/Name: Custo

Customer Code:

Rev. No.:

0

Page No.:

Page 1 of 1

No.			Work Procedure/ Illustration					Records/Remarks/ Quality Pointers
	Two Typ	es of J	pinting Method					
	1. Twisting Method							
		① Str	p 30 ∼ 50mm of the insulation using stripper.					
			the core wire to joint and twist them. Twist firmly on bot t length must be 30mm or more.	h ends.				
		-						
		-						
		N	ote: Twisted wire must not exceed the overall diameter. This method is easier to come apart than hooking			ist firmly to	the end	
			NO GOOD SAMPLE	method, 30	need to tw	ist ill filly to	the end.	
			-Short joint - below 30 mm -Not twisted until the end					
			-Twisted wire exceeds the over	all diameter	of the wire			
	2. H	lookinį	Method					
		① Str	p 40 $\sim$ 60mm of the insulation using stripper. Strip is lo	nger than tw	vist method	l.		
		@ F-1						
		(Z) F011	the core wires in half, hook and twist them.					
							-	SEE STANDARD THE SEE SEE STANDARD SERVICE SERV
								Philippines) TER COPY
	Note: Jointed wire must not exceed the overall diameter of the wire.  NO GOOD SAMPLE							
			-Short joint - below 30 mm -Not twisted until the end					
	-Jointed wire exceeds the overall diameter of the wire  Important Points:  ※ To avoid exceeding overall wire diameter, cut half (1/2) of the strands first before jointing.  ※ Tensile strength of jointed wires must be over 6kg.							
							Prepare	Check Approve
							m 26	March
Eff./Rev.Date	NBCP-1100 Doc/DRCN No.	NA Rev. No.(if	Previously established Work Instruction( for history purpose only)  Details of change	- Revise	- Check	- Approve	Z. Mendez Est. date:	0.MERIN T. SUGIYAM/ 07/10/2017