

			7N0071	TF	۲J	Rev	/. No.:	0	Page	No.:	Pag	je 1 of 1	
No.	Work Procedure/ Illustration							Records/Remarks/ Quality Pointers					
1	Spread Vinyl s folding box.	heet inside		7		700			Qty/bo	х	108	9pcs* 12bdls	
									Mat'l name	• '	Dim.	Qty.	
							The state of the s		Orico box		6*55*2 43	1	
									Vinyl shee		520* 1500	1	
									Partition		343* 510	2	
					Ped I				Viny	l ;	300* 200	12	
2	Put first bundle products. (9pcs/4bundle	s)	9pcs/4bundles Plastic vinyl bag of CSW assy							Note : Step 5 is applicable only to QC FG inspection.			
3	Layout partitio Put the produc (9pcs* 4 bund on the 2nd lay	ets (es)											
	Layout partitio	n board		2nd Laye	er				-				
4	Put the products (9pcs* 4 bundles) on the 3rd layer												
	3rd Layer								-				
5	Fold the vinyl service Put NBP Ident tag at the top. warehouse Ide tag at lower right the box.	ification Then entification	Note: If need to attach 4M tag Put 4M tag at the left side of the box										
									I				
									Prepared by	Reviewed b	y Approved I	by Noted by	
05/5/22	0 Initial	Issuance			K. Doria	J. Loterte	C. Villanueva	A. Arañes	Prepared by	Reviewed b	y Approved I	2 (20)	

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines) **MASTER COPY** May 5, 2022