No.	Work Procedure/ Illustration	Records/Remarks/ Quality Pointers

1. Request Minimum Stock Requirement for each consumable. See Table 1-1 for the list of consumables.
   *Do not overstock
   *Make sure to double check all the specifications of each item before receiving.

Table 1-1: List of consumables

Name	Specification	Stock		Unit
		Minimum	**Maximum**	
Gloves	White, Small	100	200	pairs
Green marker	TAT	5	10	cases
Ink	TAT	5	10	pack
Solvent	TAT	5	10	pack

KANBAN CARD — Process: **Contact SW Assembly** — Actual Part Picture Reference

Specification	KULIMHI
Part Name	CLEAN WIPER
Stocks Capacity	3pack

KANBAN CARD — Process: **Contact SW Assembly** — Actual Part Picture Reference

Specification	TAT
Part Name	Green marker
Stocks Capacity	10 pcs.

KANBAN CARD — Process: **Contact SW Assembly** — Actual Part Picture Reference

Specification	White, Small
Part Name	Gloves
Stocks Capacity	200 pcs

KANBAN CARD — Process: **Contact SW Assembly** — Actual Part Picture Reference

Specification	TAT
Part Name	Solvent
Stocks Capacity	10 pcs.

KANBAN CARD — Process: **Contact SW Assembly** — Actual Part Picture Reference

Specification	TAT
Part Name	Ink
Stocks Capacity	10 pcs.

			Prepared	Checked	Approved
11/09/2023	0	Newly establish Work Instruction for CSW Assy	L.Famodulan A.Ayop W.Carbillon L.Famodulan	A.Ayop	W.Carbillon
Eff./Rev. Date	Rev. No.(if applicable)	Details of change	Revise	Check	Approve
					Est. date: **11/09/2023**