


		ALL	ALL	TOV. No	10 1 ago 110 2 01.1
No.	Process	Work Procedure/ III	ustration	Tools / PPE	Records/Remarks/ Quality Pointers
		Get a plast from the c	ic of contact ontainer		
2	Contact Preparation	Carefully pour the contact from the place container (tupperware) to avoid defor			Observe proper handling: Never transfer or pick up contact using bare hands to avoid contamination, discoloration and
		e	rom its container pour only nough quatity of contact to its ay prior assembly.		In case there is a left over, return it on the covered container.




	Process Name/ Title:						
	CONTACT SWITCH ASSEMBLY/ B15C Contact Assembling				WI-PRO-COS-030		
					1		
7	WORK INSTRUCTION			ite:	March 01, 2024		
	Product Code/Name:	Customer Code:	Rev No ·	13	Page No :	3 of 7	
			REV NO:	1.5	Page No :	.5 () (


		ALL	ALL	Rev. No.:	13 Page No.: 3 Of 7
No.	Process	Work Procedure/ Illu	ustration	Tools / PPE	Records/Remarks/ Quality Pointers
			e Plate assembling ng <u>brush</u> and <u>wipes</u>	Clean Wiper	
3	Putting slider at the Plate assembly table and conducting Inspection	Proper position	Set the slider(70575-0010) on the plate assembling table.		Make sure slider leg is properly inserted to the
		1 2 3 4 5 5	Checking of slider condition must be in sequence from top to bottom then from left to right.		INCOMPLETE NAILS DAMAGED/BROKEN NAILS




		Product Code/Name:	Customer Code: ALL Rev. No.:		: 13 Page No.:		4 of 7	
		ALL			13 1 45	9		
No	. Process	Work Procedure/ Illustration		Tools / PPE		Records/Remarks/ Quality Pointers		
<u>/13</u> 4	Getting of contact from the tray using vacuum tools	tray using vacuum. position o	Vacuum the center flat part of the contact ip should be in exactly vertical on the flat center part. getting the	Vacuum.	If e posit	ncounte on of co	ered wrong ontact, switch ccuum to eact from the	



No. Process Work Procedure/ Illustration Tools / PPE Records/Remarks/ Quality Pointers Fixed the Slider using left Index Finger with support of middle Vacuum tip should be vertical to the slider during contact assembly. Check the contact sound and insertion to indicate that contact is properly inserted in the slider. Start Start Proper direction of contact assembly should start on the upper left side of the first row going to the right.			ALL	ALL	Rev. No.:	3 Page No.: 5 of 7
Fixed the Slider using left Index Finger with support of middle Vacuum tip should be vertical to the slider during contact assembly. Check the contact sound and insertion to indicate that contact is properly inserted in the slider. Start Start Fixed the Slider using left Index Finger with support of middle Avoir Touching OF CONTACT > Contact must be fully inserted to the slider. > Gap and unbalanced insertion is not allowed. > Do not forced the deformed contact to insert inside the slider. > If encountered Deform or Mis Align Contact: DISPOSE REWORK/REPAIR IS STRICTLY PROHIBITED Proper direction of contact assembly should start on the upper left side of the first	No). Process	Work Procedure/ III	lustration	Tools / PPE	
	25	Insertion of contact to the slider	Fixed to Finger Vacuu Vacuu Slider of Check insertion proper Start Proper direction of contact assembly should start Proper direction of contact assembly should start Fixed to Finger Vacuu Start Proper direction of contact assembly should start Prope	m tip should be vertical to the during contact assembly. the contact sound and on to indicate that contact is rly inserted in the slider.		AVOID TOUCHING OF CONTACT > Contact must be fully inserted to the slider . > Gap and unbalanced insertion is not allowed. > Do not forced the deformed contact to insert inside the slider. > If encountered Deform or Mis Align Contact : DISPOSE REWORK/REPAIR IS STRICTLY





		Product Code/Name:	Customer Code:	Rev. No.:	13 Page No.: 7 of 7
		ALL ALL Rev. No.:		13 Fage No 7 Of 7	
No	. Process	Work Procedure/ Ille	ustration	Tools / PPE	Records/Remarks/ Quality Pointers
7	Final Verification (Final Inspector)	contact inspect	final verificator will then put the embled slider contact in the push parts delivery which is the location		If encountered NO GOOD CONTACT or ASSEMBLED PARTS directly put it on the NG container. Note: For Drop Contact put it also in the NG Container Make sure to put all No good contact in the container and do not mix it to Good Contact. REWORK/REPAIR IS STRICTLY PROHIBITED

NBC (Philippines) **MASTER COPY** WI-PRO-COS-030

March 01, 2024