

Process Name/ Title:						
Control of Indirect	Document No:		WI-WHS-RMW-005			
WORK INSTRUCTION			ite:	June 8, 2023		
Product Code/Name:	Customer Code:	Rev. No.:	2	Page No.:	Page 1 of 5	
Common	N/A	Rev. No	ာ	rage No		

No.			Work Procedu	re/ Illustration	1						cords/Rema uality Pointe	
1	Objectiv	e / Purpose										
	stor heal	age, and issuance of differ	ded to serve as instructions for the ent chemicals stored in warehous els, material safety data sheets, PR	se. All employees	must be	aware the	e risk of p	otential p	hysical and			
2	Indirect	Materials Definition and	Approved List 🖄									
	Alte dire App	rnatively, they may be use ct materials. Thus, they ar	Is used in the production processed in such insubstantial quantities to consumed as part of the productials was posted in warehouse recitals details contains: D. Maker E. Unit of measurement(UOM)	on a per-production process.	ct basis th	at it is no ea. me		-				
3	Incomin	C. Specs g Delivery 🖄	F. Minimum order quantity(MOQ	1)	I. Lead Fr	ee product	:?					
4	* * * * * * * * * * * * * * * * * * *	B. Floorboards are di C. No evidence of ch D. Insect and rodent E. Make a note of the F. Bad odor. G. Notify the Supervi Delivery helper shall prov docking area. Delivery driver/helper shall prov docking area. Delivery driver/helper shall bring Delivery driver/helper shall bring Delivery helper shall bring Delivery Receipt (I C. Packing List (option D. PEZA documents to Check the delivery receip If with stamp, proceet If no stamp, instruct If Supplier has lackin Instruct delivery personn weight or volume of the i If the item need to use Fo Forklift operator must be Inspect the condition of t A. No damaged case B. All products are on C. No evidence of an Compare the part numbe documents against actua If correct, proceed w If discrepancy was fo For material with expirati Refer to WI-WHS-RMW-O Record the materials with Leader shall verify actual Put RECEIVED stamp on t Update the Delivery Mon Endorse the documents t	e covered and closed. ry and clean. emical spills, garbage, waste or spacetivity. e truck license plate or trailer nursisor and Quality Team of any issuride signal to their truck/trailer drailer signal to their truck/trailer drailer put oil pan under the trucks/troperators shall check trucks/trailer graph the documents to warehousem: cuments from supplier/delivery properators shall check trucks/trailer graph the documents to warehousem: cuments from supplier/delivery properators in the special state of the shipment to ensure: s or packages. In clean pallets. In one special special state of the shipment to ensure: s or packages. In clean pallets. In one special special state of the special stat	mber. es. iver until the veh urevent truck/trai ailers engine to p er wheel chock at an in charged in ersonnel: Azone Company' lier under PEZA z EZA for proper st id inform Purchas rry, Push cart, or efine location for t operator for the ender/Supervisor the materials. kpiration date of ation form. (F-W d actual expiratio by the Receiving of delivery of ma tation. ee floor. ee and put "Ove	illers from prevent and oil pan receiving. cone). tamping. sing team Pallet lifter sorting are unloading ted the producted on the HS-025) on of the night pick support terials.	any move ny leakage are propi and wait er depend and QC ins ng of item ucts being e shipping rials.	for their ling on the spection a.	d. advise. e shape, irea. d.	ору).	or DR, as (s on Invoice, Pa must be the s Company Nam ne, Quantity ar	ame such e, Item
					•		•					
	1					1	ı	1	Drong	Check	Anne:	Note -
06-08-23	3	Additional instruction for	r the verification of actual expiration date of t	the materials	E. Sanchez	M. Banaban	I. Aranas	N. Kitamura	Prepare	OHECK	Approve	Noted
07-01-22	2	Add information	ol number from WI-PUM-WHS-006 to WI-WI on Item No. 5 Materials placed in Locked Ca	abinet	E. Sanchez	M. Banaban	K. Funaki	-	000-	J.		. V- /-
01-31-22	1		erence of Document Control No. for Item no. lude schedule of training/orientation	3	E. Sanchez	M. Banaban	K. Funaki	-	E. Sanchez	M. Banaban	I. Aranas	N. Kitamura
	Rev. No.		Details of change		Revise	Check	Approve	Noted	Est. date:	September 28	2020	

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.



Process Name/ Title: Control of Indirect Materials						
		Document No:	WI-WHS-RMW-005			
WORI	Effective Date:	June 8, 2023				
Product Code/Name:	Customer Code:	Rev. No.:	3	Page No.:	Page 2 of 5	
Common	N/A	1.07.110	·	r ago rto	r age z or o	

No.	Work Procedure/ Illustration	Records/Remarks/
NO.	WOLK FLOCEGUIE/ IIIUSU AUDII	Quality Pointers
5	* List of Indirect materials that need to be inspected by QC team: A. Soldering Wire B. Grease C. Blanking/Terminal Oil D. Thermelt (Hotmelt glue) * Other indirect materials do not need to be inspected by QC team like Carton boxes, Cover pads, Corner board post, PP strap, Stretch film, Partition board, Flux remover, etc. * Issue a copy of Delivery Receipt(DR) or Packing list together with Transmittal form to QC team as their reference of	Only leaders/Supervisor and Person In charge are allowed to access the Chemical Storage
	indirect materials for QC inspection. * Put cone indication "FOR QC INSPECTION" on the materials.	
6	* After inspection of the materials needed to be inspected, warehouseman shall check if all the materials have QC Inpection Passed stamp. * Transfer the materials in sorting area.	
	* Sorting process shall based on below assigned lead-time. For Import Supplier (NBC Japan) and Local supplier - within 3 days after quality inspection. * Check and print the required Monthly Color Coding for the materials. Refer to WI-WHS-RMW-004 Actual received date was indicated on the Monthly Color Coding label. * Attach "Monthly Color Coding" in each box/packaging. * Attachment of Monthly Color Coding is after incoming quality inspection of materials. * After sorting actual parts and attachment of monthly code, locate all sorted parts to its designated location. * For indirect materials with expiration, arrangement and refilling in the storage location is from nearest expiration date of the materials.	All materials are not allowed to place directly on the floor
	Chemical Storage * For Blanking Oil/Terminal Oil, and Grease use Push cart when transferring in storage location and designated area	
	Storage location for Blanking Oil(Terminal Oil)	Only leaders/Supervisor and Person In charge are allowed to access the Chemical Storage
	* Get the key of the Chemical storage to warehouse staff and proceed to chemical storage	
	* Store chemicals properly at the storage location. * Follow FIFO when refilling of Blanking/Terminal Oil, and Grease refer to (WI-WHS-RMW-003) for the Material with Expiration.	

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.



	Process Name/ Title:						
Control of Indirect Materials		Document No:		WI-WHS-RMW-005			
	WORK	(INSTRUCTION	Effective Date:	June 8, 2023			
	Product Code/Name:	Customer Code:	Rev. No.:	3	Page No.:	Page 3 of 5	
	Common	NI/A	1101.110	~	i ago ivo	. 450000	

Records/Remarks/ No. Work Procedure/ Illustration **Quality Pointers**

N/A

Put "FIRST OUT" and "FILL" indication after storage

Common





Lock the cabinet and return the key to warehouse staff



Materials Placed in Locked Storage Cabinet

- * List of Indirect materials placed in Locked cabinet
 - A. SOLDERING WIRE
 - B. SOLDERING TIP
 - C. HEAT SENSOR
 - D. CLEANING WIRE
 - E, TAT INK DRY QUICK SOLVENT
 - G. XSTAMPER/stamp
 - H. TAT STAMPER INK
- Upon received the materials, need to prioritize for the QC inspection.
- After QC inspection immediately stored in locked cabinet for safe keeping.

Refilling:

- Refilling is from FILL sign going to the right side of the cabinet.
- Transfer the FILL sign to the last box/materials was refilled.

Refer to drawing H.



Issuance of Indirect Materials to Production (Packaging Materials, Chemicals)

For Indirect materials like Grease, Thermelt, Soldering Wire, plastics, etc.

- Collect Kanban Request Card for Indirect Materials from production for the withdrawal in warehouse storage.
- Segregation of Kanban is per part number, description, and location
- Scan the QR code in Kanban using Handy Terminal Scanner for outbound transaction and traceability(Refer to item no. 8 for the process of scanning)
- Pick item according to Kanban qty. requested

Label for Actual Parts

Kanban Request Card



ONFIDENTIAL: @2017 NBC; all rights reserved. Any misuse or isappropriation, including unauthorized copying, reproduction in any form, sclosure or publishing of this document or any information herein is strictly ohibited.



Nο.

Process Name/ Title: Document No: WI-WHS-RMW-005 **Control of Indirect Materials** WORK INSTRUCTION Effective Date: June 8, 2023 Product Code/Name: Customer Code: Page 4 of 5

Rev No:

3

Page No.:

Withdrawal: Withdrawal is from left side where the FIRST OUT sign was placed going to the right side. Refer to Drawing G.	G	
Transfer the FIRST OUT sign to the next box to be withdraw. For material with expiration date		

N/A

Work Procedure/ Illustration

*Only Authorized person (Pickers, Person-In charged) allowed to withdraw in chemicals storage and materials placed in locked cabinet location.

Records/Remarks/

Quality Pointers

For Indirect materials like Soldering wire, Soldering tip, Cleaning wire, Solvents, Ink, etc.

- Every Tuesday, Production and other department shall give Material Request Slip to Warehouse Clerk for material preparation
- Warehouse clerk shall prepare based on the material request per description and quantity needed
- After preparation warehouse clerk shall encode withdrawn items to warehouse monitoring for documentation
- Every Wednesday end-user shall get the requested items to warehouse clerk for the issuance

For Indirect materials like Blanking Oil/Terminal Oil, and other chemicals

- CnC production shall give the Kanban request card and secondary container to refill to Warehouse Picker
- Get the key of the chemical storage to Warehouse staff
- Check Kanban request what kind of chemicals needed
- Proceed to warehouse storage for withdrawal

Common


- Get and use PPE's like disposable gloves and assigned goggles before handling any chemical products at the spill kit cabinet for safety purposes
- Scan the QR code in Kanban using Handy Terminal Scanner for outbound transaction and traceability(Refer to item no. 7 for the process of scanning)
- Check the label and get the appropriate Oil Pump for each chemicals



- Check the label of chemicals based on the Kanban request to avoid wrong issuance
- Get the chemical pan and place the secondary container on top to contain any possible leakage or spill
- Remove the cap of both main and secondary container to fill
- Insert both nozzle inside the main chemical container and secondary container then pump slowly the handle until the secondary container was in full
- After refilling the secondary container, remove slowly the Oil Pump from main and secondary container
- Return the Oil Pump in the proper location to avoid using it to other chemicals and prevent any contamination
- Cover the cap for both main and secondary chemical containers
- Get the chemical pan then wipe and clean any spill using rags and absorbent mat at the spill kit cabinet
- Remove any PPE's like gloves and goggles
- For assigned goggles return it to spill kit cabinet.
- For used gloves, rags, and absorbent mat, endorse to PCO Officer for proper disposal of hazardous materials
- Lock the chemical storage and return the key to Warehouse In-charge for proper safekeeping
- Place the refilled chemicals to the CNC storage location

8 Scanning of materials ISSUANCE using KEYENCE HANDY TERMINAL

- Scan the QR code on Kanban using Keyence Handy terminal for the part no. and quantity to be picked.
- Input manually in the scanner the ship date and lot no. indicated in the material label.



*Read Material Safety Data Sheet (MSDS) for the information on the potential health effects of exposure to chemicals, or other potentially dangerous substances, and on safe working procedures when handling chemical products.

ONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or isappropriation, including unauthorized copying, reproduction in any form, sclosure or publishing of this document or any information herein is strictly



	Process Name/ Title:			WI-WHS-RMW-005			
7	Control of	Document No:					
	WORI	KINSTRUCTION	Effective Date:		June 8, 20)23	
4	Product Code/Name:	Customer Code:	Rev. No.:	2	Page No.:	Page 5 of 5	
	Common	N/A	INGV. INU	J	i age ivo	rage 3 01 3	

No.	Work Procedure/ Illustration	Records/Remarks/ Quality Pointers

9 In case there is a chemical spillage

* In the event of a chemical spill, warehouse member(s), who caused the spill is responsible for prompt and proper clean-up.

It is also their responsibility to have spill control and personal protective equipment appropriate for the chemicals being handled readily available.

General Response Guidelines

Small Spills - Spills of less than 4 liters of material that you know the hazards of and that you have the ability to clean up.





Large / Potentially hazardous Spills - Spills of greater than 4 liters or material presents an immediate fire, safety, environmental, or health hazards.





For simple spills, emergency responders do not need to be notified. However, you should contact the Environmental Health and Safety Officer or other responsible person within the facility. Most importantly, before cleaning up a simple spill, be sure that you can do so safely. You must have the right personal protective equipment, appropriate eye protection and protective gloves. Additional protective equipment may be required for spills that present special hazards (such as corrosive or reactive spills or spills that have a splash potential)

The following steps should be taken during spill cleanup.

- * Prevent the spread of dusts and vapors.
- * Control the spread of the liquid
- * Absorb the liquid. Add absorbents to the spill, working from the spill's outer edges toward the center
- * Collect and contain the cleanup residues. The neutralized spill residue or the absorbent should be scooped, swept, or otherwise placed into a plastic bucket or other container. Be sure to place descriptive labels on each container.
- * Keep cleanup materials separate from normal trash. Contact the environmental health and safety officer for guidance in packaging and labeling cleanup residues.
- * Decontaminate the area and affected equipment.

Note: All RM / FG warehouse team member including(Manager, Supervisor, Staff, Warehouseman) shall undergo refresher training/orientation of this work instruction twice a year (January and July).

After orientation every warehouse member shall undergo examination after the training/orientation for the process re-certification.