
			WORK INSTRUCTION Effect								tivity Date:		January 26, 2024			
NE			Process Name/Title: TAPING ASSEMBLY PROCESS							Validi	ity Date:		n/a			
			Model code/Part number:	ES1 /	7M0515-7021	Customer:	TRJ Car Mod	el: S	UBARU	Docu	ment No.:		WI-ENG-PDE-7	70B		
			Purpose:	PROTOTYPE		PRE-LAUNCH	MA	SSPRO		Revis	sion No.:	0	Page No.:	1 of 4		
PARTS:		1. All pa	arts: Assy parts; Black tape							JIG:	n/a	n/a				
N	NO. PROCESS NAME				WORK PR	ROCEDURE/ ILL	USTRATION				TOOLS/PPE		QUALITY POIN	TERS		
	NO. PROCESS NAME TABLE LAY-OUT Assy parts Black tape/ Tape holder							(gld	afety Instruction Be sure to wear orescribed personal otective equipme during operation oves, finger cots, etc. Housekeeping Maintain and alwar practice 5's. Personal things of the workplace is rohibited. Keep it if your locker. Alert level or any trouble, inforce Assembly Assists. Supervisor or Line eader for immedia corrective action.	al nt tetc.) iys length on tetc. 1. No miss 2. No excerment tetc.	No missing parts/tools No excess parts/tools					
					Revision History					ı	Prepared by	Reviewed by	Approved by	Noted by		
						-				•						
		-														
01/26/24		Initial issue. Additional Important reminders/Note/s in Half wrap taping due to customer claim countermeasure (Page 3). D.Castillo C. Villanueva A. Arañes n/a O. Castillo C. Villanueva A. Arañes O. Castillo C. Villanueva A. Arañes							n/a							
Eff. Date	Rev. No			Details of Cha	nge		Revise	d Reviewed	Approved	Noted	Est. Date:	January 26, 2024				



	_			WORK INSTRUCTION	Effectivity Date:	January 26, 2024					
		Process Name/Title:	Validity Date: n/a								
		Model code/Part number:	TAPING ASSEMBLY PROCESS ES1 / 7M0515-7021 Customer: TRJ Car Model: SUBARU					Document No.:	WI-ENG-PDE-770B		
		Purpose:	PROTOTYPE	□ PRE-L		MASSPRO		Revision No.:	0	Page No.:	3 of 4
	•										
PARTS:	1. Assy parts 2. Black tape [1pc]							JIG:	n/a		
NO.	F	ROCESS NAME	WORK PROCEDURE/ ILLUSTRATION					TOOLS/PPE	(QUALITY POIN	TERS
3	P2	Half-wrap Taping 2	L 1/2 shift	1/2	begin taping 2. M	lake 1/2 shifting. less until the end e 3 winds and th	. Repeat the of corrugated tube.	MEASURING	1. Please measure measure 2. Used the tape BLACK 3. Interesting 1. No flip-c2. No peel-3. No loose 4. No miss	d WHITE TAPE to be shifting, but actual TAPE. mal tolerance for his should be 0~14min but tape -off tape e tape	erified ting the easily visualize al should be

			WORK INSTRUCTION							
	Effectivity Date:	January 26, 2024								
	Process Name/Title:		TAPING ASSEMBLY PRO	Validity Date:	n/a					
	Model code/Part number:	ES1 / 7	M0515-7021 Customer: TRJ	Car Model:	SUBARU	Document No.:		WI-ENG-PDE-77	70B	
	Purpose:	PROTOTYPE	☐ PRE-LAUNCH	MASSPRO		Revision No.:	0	Page No.:	4 of 4	
PARTS: n/a						JIG:	n/a			
			QUALITY CHI	ECKPOINTS						
P2			71/10	51 7	M21					
PZ			7M0!	DTD-1	UZI					
			I deadle de Al Al Al Al Al	and to have been						
			HUU BULLING	1 Little	ti ti					
			A COLUMN TO THE REAL PROPERTY AND ADDRESS OF THE PARTY AND ADDRESS OF T							
						(1)			X.	
				2						
	Children of the same of the sa					AND THE PARTY OF T			A S	
		444		er er erfen ender Server en re Servelfic er et fer er er er er er er er er	the state of the second of the state of the	With the second				
				A Second	V-28-40					
				_						
	1 No MISSING TAPE (2) CHECK HALF WRAP TAPING									
	1 No MISSING TAPE 2 CHECK HALF WRAP TAPING									
				_						
							-			