

Process Name/ Title:						
Wire Taping Parts Pre	eparation Procedure	Document N	No:	WI-PRO	D-KIT-0011	
WORK INST	RUCTION	Effective Da	ate:	January 13, 2023		
Product Code/Name:	Customer Code:	Rev. No.:	0	Page No.:	1 of 2	
		INCV. INU		raye No	1012	

			SAKIMELT MODELS	ALL		Rev. No.:	<b>0</b> F	Page No.:	1	of 2
No.	Work Procedure/ Illustration							ords/Rem ality Poin		
1	on the racl	k and	s preparation will get the Identification t Daily Operation Report based y plotted plan.	ag			100	Daily Identificat	Operation Rep ion Tag must b model	port and be the same
2	based on I Conduct so on each tu	Parts ampli ube in	Vinyl tube on the parts rack Preparation Card. ng check of length and counting every first bundle. on models that have Vinyl Tube)						oundled of wire of tube per bu 200 pieces.	
3	on the par removed o	rts rac one pi	f wire, get the needed quantity of wire k. Removed paper on the bundled wire, ece rubber band on the smaller size of t ng length and count of wire in every first	erminal side.				No ter	minal defo	rmation
4	Set one pi	iece o ox, pu ube th	t the counted en fold the							
5			eeded details in sub assy Identification o., Shift, Date, Operator, Start time and I					No	) wrong de	tails
6	Fill out Change Point Control Tag (4M change) and attached to the lower right portion of the identification tag (if needed).							No wrong attachment of 4M		
		ļ						Prepare	Check	Approve
01/13/2023	0	<u> </u>	New Issue		B. Maloles	M. Cruzat	O. Merin	B.Maloles	M. Quzat	Q. Merin
Eff./Rev. Date	Rev. No.		Details of change		Revise	Check	Approve	Est. date:	01/13/2	2023

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY



Process Name/ Title:							
Wire Taping Parts Preparation Procedure			0:	WI-PRO	WI-PRO-KIT-0011		
WORK INSTRUCTION			e:	January 13, 2023			
Product Code/Name:	Customer Code:	Rev. No.:	0	Page No.:	2 of 2		
		1167.110	U	raye No	2012		

		SAKIMELT MO	DELS	ALL	Rev. No.:	<u> </u>	Page	: NO.: 2 OT 2
No.			Work Procedu	re/ Illustration				Records/Remarks/ Quality Pointers
7	Attach identific It must be arra	ation tag in front of box. nged based on the ID No.	consecutively.					FIFO should be maintained always
8	Daily Operatio (Date, Shift, ID NG details and	data of prepared parts in on Report (Parts Setting) (F o No., Qty., Wire and VT de I Remarks). d box to Wire Taping Area.	etails, Prepared by:,					No wrong details

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY