

Process Name/ Title: Wire Cutting and Crimping / Crimp Shape Check

Document No:

WI-PRO-CNC-026

July 10, 2017

WORK INSTRUCTION Product Code/Name: ALL

Customer Code: ALL

Effective Date: Rev. No.:

0

Page No.:

Page 1 of 1

			ALL ALL	
No.			Work Procedure/ Illustration	Records/Remarks/ Quality Pointers
	Checkpo  ① Crimp			
	Che			
	② Bend 7			
		Par	rallel Parallel	
		*Criter	ia: If there is no instruction : ± 3°	
	③ Twist a	and Rol	ling	
			Twist Rolling	,
		*Criter	ia: If there is no instruction : ± 3°	
	④ Cut off Tab Burr			_
	End Type Terminal Side Type Terminal			
	F.		Check burrs on both front edge and rear edge.  Check on burrs at rear end.	
	*Criteria: There should be no burrs.			
	⑤ Smashed Terminal (female), Opening (male)			
				y.
			female male	
		*Criter	ria: There should be no crush and no opening.	NBC (Philippines)
	⑥ Bell-M	NBC (Philippines) MASTER COPY		
	E			
	Note : * M * In	WI-PRO-CNC-015		
			Prepa	re Check Approve
			M.Garc	
- Eff./Rev.Date	NBCP-1076 Doc/DRCN No.	NA Rev. No.(if applicable)	Previously established Work Instruction( for history purpose only) Z. Men  Details of change Revise Check Approve Est. date	