

Process Name/ Title:						
Cleaning Wire-Solo	ler Waste Disposal	Document No:	WI-PRO-COM-027			
WORK INSTRUCTION		Effective Date:	February 15, 2024			
Product Code/Name: ALL	Customer Code: ALL	Rev. No.:	0	Page No.:	1 of 1	

	ALL ALL						I	Records/F	Remarke/	
No	Work Procedure/ Illustration						Quality F			
No.		Details of work	Illustration		Checkpoint					
1		aning Wire holder to yellow box for cleaning	BEFORE CLEANING	When solder waste is difficult to remove or harden. When some wire starts to worn out.						
2	Remove the upper cover and take out the cleaning wire			Dispose solder waste after operation						
3	Unravel cleaning wire in trash can (intended only for solder waste), Rub to remove solder waste.			DO NOT USE ESD GLOVES WHEN CLEANING OF SOLDER WASTE. USE THE RUBBER GLOVES PROVIDED Compare to boundary sample			WIF SC RE	CHANGE CLEANING WIRE IMMEDIATELY, IF SOLDER RESIDUE IS DIFFICULT TO REMOVE, HARDEN OR SOME WIRE STARTS TO WORN OUT.		
4	Put cleaning wire into holder. (Clean side has to face to bottom)			If wire is sticking out of case, cut wire and reduce volume.			cut			
5	Put cleaner into blue box after cleaning Return to each line after.		CLEANING							
					Prepared	d Checke	d Approved			
02/15/2024 Eff./Rev. Date			049 of CSW and WI-PRO-SHM-001 of Hotmelt. Details of change	noit.		W.Carbillon Approve	A.Ayop Est. date	A.Ayop C.Calayan W.Carbillon Est. date: February 15, 2024		

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited. NBC (Philippines)

MASTER COPY