	WORK INSTRUCTION Process Name/Title: TAPING ASSEMBLY PROCESS									Effectivity Date: July 5,			3	
		F	Process Name/Title:		TAPING ASSEMB						ity Date:		-	
		N	Model code/Part number:	890B / 7L0100-70	Customer:	TRQSS	Car Model:	TOYO	TA-C-SL	JV Docu	ment No.:		WI-ENG-PDE-4	05B
		F	Purpose:	PROTOTYPE	PRE-LAUNCH	1	MASSP	PRO		Revis	sion No.:	3	Page No.:	1 of 7
PARTS:	O.	1. Assy p	Parts; Clamp 82711-52090 ROCESS NAME Table lay-out	0 (W); Black tape [3pcs]	TABLE LA Assy Parts Tape holder/ Black Tape	/ ILLUSTRA		-52090 Tray	TOWASSEMENT PROPERTY IN THE PR	S. S. P.	JIG: TOOLS/PPE afety Instructi Be sure to wear orescribed person otective equipm during operation gloves, finger conetc.) Housekeeping 1. Maintain and always practice 5'. Personal things the workplace is rohibited. Keep it your locker. Alert level For any trouble, form the Assembles is sistant Supervisor Line Leader formediate correctinaction.	1. Clamp A	Assembly Jig QUALITY POIN CLAMP ILLUSTRATIC	ITERS
		•	•	Revision		-				•	Prepared by	Reviewed by	Approved by	Noted by
07/05/23	l .		•	nent from 25mm to tape width; change to	emplate, inclusion of Car Mod	del		C. Villanueva	A.Arañes	n/a				
05/10/23	1		of quality checkpoints Vork procedure/Illustration on	process no. 2,3 ,4, 5 and 6; Quality poir	nters and notes on pg. no. 1, 2	2, 3, 4, 5 and 6	J. Loterte M. Ariola	C. Villanueva J. Loterte	A.Arañes C. Villanueva	n/a A. Arañes		1/-b-it	Alan	
02/11/22	0	Initial Issue	e. PCB 2 chips (61C619-0002	2) to 1 chip (7N0994-7060) Wire color of	f Gray (GR) to Green (G)		M. Ariola	J. Loterte	C. Villanueva	A. Arañes	J. Loterte	C. Villanueva	A.Asañes	n/a
Eff. Date	Rev. No			Details of Change			Revised	Reviewed	Approved		Est. Date:	February 11, 2022		



	_		WORK INSTRU	JCTION			Effectivity Date:		July 5, 2023	
		Process Name/Title:		ASSEMBLY PROCE	ESS		Validity Date:		-	
		Model code/Part number:	890B / 7L0100-7021	Customer: TRQSS	Car Model:	TOYOTA-C-SUV	Document No.:		WI-ENG-PDE-40)5B
		Purpose:	PROTOTYPE	PRE-LAUNCH	☐ MASSPRO)	Revision No.:	3	Page No.:	2 of 7
PARTS:	1. Clam 2. Black	p 82711-52090 (W) [2pcs] tape [2pcs]					JIG:	1. Clamp As	ssembly	
NO.	F	PROCESS NAME	WORK PRO	CEDURE/ ILLUSTRA	TION		TOOLS/PPE	(QUALITY POIN	TERS
2	P2	Clamp setting		-52090 Laboth	Black tape of s.	SWITCH ASSEMBLY PASSEMBLY PASSEMBLY NBC NBC		1. Please of assemparts. 1. No dama 2. No wron 3. No wron	aged clamp g use of parts g use of tape DARD TAPING F ne side tape unde	obefore starting use of

			WORK IN	STRUCTION			Effectivity Date:		July 5, 2023	
		Process Name/Title:	TAPI	NG ASSEMBLY PROC	ESS		Validity Date:		-	
		Model code/Part number:	890B / 7L0100-7021	Customer: TRQSS	Car Model:	TOYOTA-C-SUV	Document No.:		WI-ENG-PDE-40	05B
		Purpose:	PROTOTYPE	PRE-LAUNCH	☐ MASSPR	RO	Revision No.:	3	Page No.:	3 of 7
PARTS:	1. Assy 2. Blac	parts k tape					JIG:	n/a		
NO.	F	PROCESS NAME	WORK	PROCEDURE/ ILLUSTR/	ATION		TOOLS/PPE	(QUALITY POIN	TERS
3	P2	Taping 1 COT to wire near connector	1. Hold the corrugated using left hand. Get Black tape using right hand and start pre-taping using both hands. 25±3mm L 25±3mm L 3. Measure the end of the corrugated to the edge of connector 25mm. Then contaping using right hand.	Tape wide	tape width from the taping process.	om end of tape up to ess using both hands.		1. Please measure measure 1. No peel 2. No flip of 3. No loose 4. No wron	-off tape ut tape e tape g use of tape g dimension	erified

				NSTRUCTION		Effectivity Date:		July 5, 2023	
		Process Name/Title:	TAP	ING ASSEMBLY PRO	CESS	Validity Date:		-	
		Model code/Part number:	890B / 7L0100-7021	Customer: TRQSS	Car Model: TOYOTA-C-SUV	Document No.:		WI-ENG-PDE-405	5B
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	3	Page No.:	4 of 7
PARTS:	1. Assy	parts				JIG:	1. Clamp As	ssembly jig	
NO.	F	PROCESS NAME	WORI	K PROCEDURE/ ILLUSTF	RATION	TOOLS/PPE	(QUALITY POINT	ERS
4	P2	Clamp Assembly	1. Get the assy part and set into jig. 6189-0451 (W) to Receiver base 1 clamp. Continue if the sequence lig 2. Check if all LED light for POWEI location 1 is ON. If encountered ab WAIT for further instruction then cordinated start taping (3 windings) using both hands. Press the SW button after taping. Continue to location (2) if light was on.	1. Last, set the terminal within the office of location 1 was ON. R ON, CLAMP ON was ON. Chancements of the concernation of t	tion 5. Conduct POINT CHECKING before	n/a	600D 82711-5 1. No wron 2. No wron 3. No dam. 4. No wron	ag use of parts aged clamp go clamp position go use of clamp	ATION 2711-12A80 (W)

		1	WORK II	NSTRUCTION		Effectivity Date:	1	July 5, 2023	
		Process Name/Title:		ING ASSEMBLY PROCE	25	Validity Date:			
		Model code/Part number:	890B / 7L0100-7021		ar Model: TOYOTA-C-SU			WI-ENG-PDE-4)5B
		Purpose:	PROTOTYPE	· ·	MASSPRO	Revision No.:	3	Page No.:	5 of 7
	1 Δςς	embled parts							
PARTS:	2. Mas	ter sample				JIG:	n/a		
NO.	F	PROCESS NAME	WORI	K PROCEDURE/ ILLUSTRAT	ION	TOOLS/PPE		QUALITY POIN	TERS
5	P2	Visual Inspection	ACTUAL PRODUCT Master sample Assembled parts 1. Conduct alignment of harness (Master sample vs. Assembled parts) using both hands.	2. Check the connector lock and insertion	4. Check the taping condition and terminal 3. Ch	eck the presence of clamp he taping condition.	GOOD	MASTER SAM	

			WORK INSTR	RUCTION		Effectivity Date:		July 5, 2023	
		Process Name/Title:		ASSEMBLY PROC	ESS	Validity Date:		-	
NBC		Model code/Part number:	890B / 7L0100-7021	Customer: TRQSS	Car Model: TOYOTA-C-SUV	Document No.:	WI-ENG-PDE-405B		
		Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPRO	Revision No.:	3	Page No.:	6 of 7
PARTS:	1. Assy	parts					n/a		
NO.	F	PROCESS NAME	WORK PR	OCEDURE/ ILLUSTR	ATION	TOOLS/PPE	C	QUALITY POINT	ERS
6	P2	Measurement	122±3mm 0~5mm	302±3mr		EASURING TAPE	1. Please measurin measurer	at reminders/Note/se use calibrated/ve. ng tape when gettinent. ng dimension	rified

		WORK IN	ISTRUCTION			Effectivity Date:		July 5, 2023	
	Process Name/Title:		NG ASSEMBLY	PROCESS		Validity Date:		-	
	Model code/Part number:	890B / 7L0100-7021			TOYOTA-C-SUV	Document No.:		WI-ENG-PDE-4	05B
	Purpose:	PROTOTYPE	PRE-LAUNCH	MASSPF		Revision No.:	3	Page No.:	7 of 7
PARTS: n/a						JIG:	n/a		
			QUALIT	Y CHECKPOINTS					
P2			7	L0100-7	7021				
				EN CANE MANAGEMENT	Allianos				
京田井			· ·		WINTER FRANCES OF THE STREET				
September 1		(3)	THE RESIDENCE OF THE PARTY OF T	AND CONTRACT					
									1
GOOD	(2			# Mile					
Account to									
		A STATE OF THE STA							
									(5)
NO GOO						(Padansa)			
	(1)No	Unlocked/ Half L	ocked Cor	nnector	(3)(4)	No Missing	clamp		
	2 Na	missingtape			(5)	No Deforme	. 		
	(Z /NO	missiny tane			\ _3 /	NA LIGIARMA	A TOPMI	771	