

Process Name/ Title: Wire Cutting and Crimping / High Speed Machine Adjustment Method

WI-PRO-CNC-047

July 10, 2017

WORK INSTRUCTION

Product Code/Name: Customer Code:

Rev. No.:

Document No:

Effective Date:

Page No.:

Page 1 of 1

		ALL	ALL	Rev. No.:	0	Page No.:	Page 1 of 1
No.			Work Procedure/ II	lustration			Records/Remarks/ Quality Pointers
	Height	and Terminal Feed Adjust	ment				
	Crimp Scr	een Display					
		Front Crrsp 1 Crnp 1	SACRATION DOODS				



Height Adjustment

Adjust the height by « + » or « - », up to 0.05 mm

If height is already 0.05 mm above change the lower applicator's spacer. (0.05mm spacing)



Crimp Height Spacer



Insu-height Spacer

② Feed Adjustment

If terminal does not reach the upper blade, adjust with $\langle\!\langle + \rangle\!\rangle$ or $\langle\!\langle - \rangle\!\rangle$



NBC (Philippines) MASTER COPY

							Prepare	Check	Approve
							O Carcia/	Chip	S
-	NBHS -1705-2	NA	Previously established Work Instruction(for history purpose only)	-	-	-	Z. Mendez	O.MERIN	T. SUGIYAMA
Eff./Rev.Date	Doc/DRCN No.	Rev. No.(if applicable)	Details of change	Revise	Check	Approve	Est. date:	07/10/2	017