
WORK INSTRUCTION								Effectivity Date:	Effectivity Date: October 01, 2024				
			Process Name/Title:		MP ASSEMBLY PRO		Validity Date:		n/a				
			Model code/Part number:	J34A / 7L0105-7020H							WI-ENG-PDE-1076		
			Purpose:	PROTOTYPE	☐ PRE-LAUNCH	MASSPRO	)		Revision No.:	1	Page No.:	1 of 4	
PARTS:		1. Assy parts; Blue Tape			JIG:	1. Clamp As	1. Clamp Assembly jig						
NO. PROCESS NA			PROCESS NAME	WORK	TOOLS/PPE	(	QUALITY POINT	ERS					
1		CLAMP		TATE DESCRIPTION OF THE PROPERTY OF THE PROPER	mbly Jig	Safety Instruction  Be sure to wear  prescribed personal  protective equipment during operation (gloves, finger cots, etc.)  Housekeeping  1. Maintain and always  practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.	1. No misis 2. No exce	Document reference/s:  1. Refer to WI-PRO-CNC-071 Wire and Strip Length Tolerance  1. No misisng parts/tools 2. No excess parts/tools 3. No wrong position of parts/tools					
				Revision History	Blue Tape/ Tape Holder	2456709117734	3474518		Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leade for immediate corrective action.  Prepared by	r	Approved by	Noted by	
10/01/24	1 (	Change '	pre-launch to mass pro".			A.Hernandez C.V	Villanueva	A.Arañes r	n/a	South Tittour	400		
09/24/24		Initial iss	ue.			A.Hernandez C.V	Villanueva	A A ~		C.Villanueva	A.Arañes	n/a	
Eff. Date R	lev. No			Details of Change		Revised Re	eviewed	Approved No	oted Est. Date: Se	ptember 24 , 2024	1		

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

			October 01, 2024							
		Process Name/Title:	CLAN	Validity Date: n/a						
		Model code/Part number:	J34A / 7L0105-7020H Customer: TRQSS Car			MAZDA MX	Document No.:	WI-ENG-PDE-1076		
		Purpose:	☐ PROTOTYPE	PRE-LAUNCH	■ MASSPR	0	Revision No.:	1	Page No.:	2 of 4
PARTS:	1. Assy 2. Blue	parts tape (10mm) [1pc.]					JIG:	1. Clamp A	ssembly jig	
NO.	F	PROCESS NAME	WORK	TOOLS/PPE	QUALITY POINTERS					
2	CLAMP	Clamp Assembly	Receiver base 1  1. Get the assy parts and set to teste picture for correct setting). First, se 1 then lock. Continue to set the harnewithin the stopper jig then press by to light in location 1 was ON.  2. Check if the Clamp is ON. Check if encountered abnormality, STOP and leader. WAIT for further instruction the stopper justing both hands on location that the stopper justing both hands on location cut the tape. Press the SW butter Go sound will be heard.	r jig using both hands. (See to the 7182-8049 (W) to Recess, last set the L-B/W wire regale clamp. Continue if the follocation 1 sequence light wimmediately CALL the attention continue the process.	above eliver base is together sequence as ON. If thion of the	Make sure no gap stopper jig.  OINT CHECKING before	Counter  Clamp: On  Counter  Clamp: Off	1. Make and Terr 2. Count harness allowed  1. No wron 2. Make su stopper jig 3. No wron	nt reminders/Nor sure no gap between minal er will be the basi per box. Only <u>LE</u> , to reset the count g insert ure no gap between g use of tape ss windings	een stopper jig s of quantity of <u>ADER</u> are er.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.



CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

		WORK INSTRUCTION							Effectivity Date:	October 01, 2024		
		Process Name/Title:	CLAN	Validity Date:	n/a							
		Model code/Part number:	J34A / 7L0105-7020H	Cust	tomer:	TRQSS	Car Model:	MAZDA MX	Document No.:		WI-ENG-PDE-1	076
		Purpose:	PROTOTYPE	PRE-	LAUNCH		■ MASSPRO		Revision No.:	1	Page No.:	4 of 4
PARTS:	n/a								JIG:	n/a		

## **VISUAL INSPECTION/ QUALITY CHECKPOINTS**

## **CLAMP ASSY**

## 7L0105-7020H



- 1 No Missing Tape
- (2) (Black Tape)
- 3 No Missing Spot Tape (BlueTape)

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.