

Records/Remarks/ Work Procedure/ Illustration No. **Quality Pointers** Parts Quality Check Check and confirm materials before, during and after work because a number of defects are found in the lot such as incorrect terminals, wires and wire length. (1) Check if the terminals and wires are same based on wire cutting ledger. Terminal Reel 070 (O) Label Wire Cutting Ledger Wire Bundle Terminal Check if the part number written on the terminal reel label is the same with what is written on the wire cutting ledger. Wire Check if the details written on the label is the same as what is written on the wire cutting ledger. (2) At the end of work, recheck if the terminals and wires are correct by comparing the individual labels with wire cutting ledger. Length Quality Check ① After set up, produce sample crimped wire based on the cutting length written in wire cutting ledger. Refer to WI-PRO-CNC-011 for wire length Measure wire length and write actual measurement on daily report. (This is to check the actual measurement is the same with what is written in the wire cutting ledger.) procedure (2) At the end of work, measure the last piece of crimped wire, write the actual measurement on daily report and compare with cutting length written in wire cutting ledger. Prepare Approve J.Garcia

Page 1 of 1

Z. Mendez

Est. date:

Approve

MERIN

07/10/2017

T. SUGIYAMA



NBCP-1020

Doc/DRCN No.

Eff./Rev.Date

Revise

Check

Previously established Work Instruction( for history purpose only)

Details of change