

				Effectivity Date:	October 3, 2024						
			Process Name/Title:	CLA	Validity Date:	n/a					
			Model code/Part number:	311D / 7L0155-7023	Customer: TRQSS	Car Model: TOYO	OTA RAV4	Document No.:		WI-ENG-PDE-108	6
			Purpose:	☐ PROTOTYPE	PRE-LAUNCH	MASSPRO		Revision No.:	0	Page No.:	1 of 7
PARTS:		1. Assy parts; Clamp 82711-48210 (		3); Clamp 82711-33650 (B); Clamp 82711-3A540 (W); Black tape [4pcs]				JIG:	1. Clamp assembly jig		
N	Ο.	PROCESS NAME WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	(	QUALITY POINT	ERS			
Table Lay-out  Clamp 82711-3A540   lamp 82711-33650   Be s prescriptoctic durin (gloves)  1 Clamp Assy Table Lay-out  Assy parts  Clamp assembly jig  Afror any the Asse Super Leader						Safety Instruction Be sure to wear prescribed personal protective equipment during operation (gloves, finger cots, etc.)  Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.  Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.	No missing parts/tools     No excess parts/tools  Approved by  Approved by  Noted by				
				Revision History	/			Prepared by R	eviewed by	Approved by	Noted by
10/03/24				Initial issue.		A.Hernandez C.Villanueva	A. Arañes	Okincon de /	out form Villanueva	A. Aranes	n/a
Eff. Date	Rev. No			Details of Change		Revised Reviewed	Approved N	oted Est. Date: Ocotb	er 3, 2024		


**MASTER COPY** 



			WORK INSTR	Effectivity Date:	October 3, 2024					
		Process Name/Title:	CLAMP A	Validity Date:	n/a					
		Model code/Part number:	311D / 7L0155-7023			ΓΑ RAV4	Document No.:		WI-ENG-PDE-1	086
		Purpose:		PRE-LAUNCH	■ MASSPRO		Revision No.:	0	Page No.:	3 of 7
PARTS:	1. Assy parts 2. Black tape [4pcs]						JIG:	1. Clamp a	ssembly jig	
NO.	PROCESS NAME		WORK PROCEDURE/ ILLUSTRATION				TOOLS/PPE	G	<b>UALITY POIN</b>	TERS
3	Clamp Assy	Connector Lock	1. Put the connector into locking jig using right hand then press 2x to lock using both hands. Check the lock if properly locked.	Double Unlock Condition	Half Lock Condition Full Lo	Double Dock Condition	4	1. WANUADAMAGE	or reminders/No.	CAUSE



		WORK INSTRUCTION Effectivity Date:							October 3, 2024			
		Process Name/Title:		ASSEMBLY PROC		Validity Date:	n/a					
		Model code/Part number:	311D / 7L0155-7023	Customer: TRQSS	Car Model: TOYOTA RAV4	Document No.:		WI-ENG-PDE-10	986			
		Purpose:	☐ PROTOTYPE ☐	PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	5 of 7			
PARTS:	1. Assy	parts		JIG:	1. Clamp assembly jig							
NO.	F	PROCESS NAME	WORK PRO	OCEDURE/ ILLUSTR	ATION	TOOLS/PPE	(	QUALITY POINT	TERS			
		Clamp assembly (Continuation)	5. Hold the tape on the clamp location no. 3 Make 3 windings of tape using both hands Press the SW button after taping. Continue was ON.  7. Hold the tape on the clamp location no. 5 Make 3 windings of tape using both hands Press the SW button after taping. Go sound	using right hand. then cut the tape. to location 4 if light  5 using right hand. then cut the tape.	6. Hold the tape on the clamp location Make 3 windings of tape using both h Press the SW button after taping. Collight was ON.  8. After taping, conduct POINT CHEC the harness from jig	no. 4 using right hand. nands then cut the tape. ntinue to location 5 if	1. Please before s avoid wr  1. No wrong 2. No wrong 3. No dama		o first embly to			



	C							Effectivity Date:	October 3, 2024			
		Process Name/Title:	CLAMP ASSEMBLY PROCESS					Validity Date:	n/a			
		Model code/Part number:	311D / 7L0155-7023	Customer:	TRQSS	Car Model:	TOYOTA RAV4	Document No.:		WI-ENG-PDE-1	086	
		Purpose:	☐ PROTOTYPE	PRE-LAUNCH	ł	MASSPR	0	Revision No.:	0	Page No.:	7 of 7	
								1				
PARTS:	n/a							JIG:	n/a			

**VISUAL INSPECTION/ QUALITY CHECKPOINTS** 

**CLAMP ASSY** 

7L0155-7023



- 1 No Half locked/Unlocked **Connector**
- **Alignment**
- Check the Clamp (3) No Missing Clamp

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.