



	WORK INSTRUCTION						September 08, 2023			
	Process Name/Title: CLAMP ASSEMBLY PROCESS					Validity Date: n/a				
	Model code/Part number:	700B / 7N0039-7020A Customer: TRJ Car Model: TOYOTA-LAND CRUISER			Document No.:		WI-ENG-PDE-732			
	Purpose:	☐ PROTOTYPE	PRE-LAUNCH	MASSPRO		Revision No.:	0	Page No.:	1 of 6	
PARTS: 1. Assy p	1. Assy parts; Clamp 82711-52090 (W); Clamp 82711-48070 (GR); Clamp 82711-3A540 (W)					JIG:	1. Clamp as	Clamp assembly jig		
NO. PF	PROCESS NAME WORK PROCEDURE/ ILLUSTRATION			TOOLS/PPE	G	QUALITY POINTERS				
1 n/a	Table lay-out	Clamp 82711-48070 (GR)/Clamp tray	Tape holder/Black tape	Clamp 8 52090 Clamp  Tape holder/Gree tape	(W)/ tray	Safety Instruction Be sure to wear prescribed persona protective equipme during operation (gloves, finger cots etc.)  Housekeeping 1. Maintain and alwa practice 5's. 2. Personal things of the workplace is prohibited. Keep it i your locker.  Alert level For any trouble, info the Assembly Assist: Supervisor or Line Leader for immedia corrective action.	1. No missi 2. No excess 3. 6000  ays  min  Importan 1. Pleasus start of a use of column ant external	nt reminders/Not e check the clam assembly to avo	p before	
1 1			Revision History	<del> </del>		Prepared by	Reviewed by	Approved by	Noted by	
	process from WI-ENG-PDE-71 S to CLAMP ASSEMBLY PRO		ocess; Change process name from TAPING ASSEMBLY lay-out. Improve Work procedure/Illustration on process	M. Ariola J. Loterte  Revised Reviewed	Villanueva	m.Agola  oted Est. Date:	J. Loterte September 08, 2023	o /ouf ) form	A Arades	
INOV. INO		Details of CII	ango	Trevised Treviewed	Approved NO	otou Lat. Date.	Coptombol 00, 2023			











WORK INSTRUCTION	Effectivity Date:	September 08, 2023									
Process Name/Title: CLAMP ASSEMBLY PROCESS	Validity Date:	n/a									
Model code/Part number: 700B / 7N0039-7020A Customer: TRJ Car Model: TO	YOTA-LAND CRUISER Document No.:	Occument No.: WI-ENG-PDE-732									
Purpose: □ PROTOTYPE □ PRE-LAUNCH ■ MASSPRO	Revision No.:	0 Page No.: 6 of 6									
PARTS: n/a	JIG:	n/a									
QUALITY CHECKPOINTS											
7N0039-7020A											
GOOD GOOD  NO GOOD  NO GOOD  NO GOOD  NO GOOD  NO Wrong to the color of tap (on 3 connector)  No Wrong Insert (on 2 connector)  Checking of Clamp alignment orientation	use of tape Clamp/No wrong e	GOOD  NO GOOD  No Deformed terminal									