





	Process Name/ Title:					
	Wire Cutting and Crimping /		Document N	lo:	WI-PRO-CNC-071	
	Proper Set-up of Terminal on Regular Machine					
7	WORK INSTRUCTION		Effective Da	te:	June 19, 2023	
4	Product Code/Name:	Customer Code:	Rev. No.:	0	Page No.:	2 of 2
	ALL	ALL	Tev. No	J	rage No	2012

No. Work Procedure/ Illustration Records/Remarks/ Quality Pointers

8 Open the safety cover



Safety Cover

9 Unlock applicator





Pay attention to terminal deformation.

10 Press feed finger and insert teminal until reached the position of crimper.



11 Lock applicator and close the safety cover



- 11 Manually feed the terminal
 - -Conduct step by step to crimp the terminal.
 - -Produce sample
 - -Proceed to mass production.

If encountered any problem perform STOP, CALL and WAIT

CONFIDENTIAL: ©2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited. NBC (Philippines)

MASTER COPY