

No. Work Procedure/ Illustration Records/Remarks/
Quality Pointers

<u> 2</u>



Put hair and ear inside cap (To avoid hair falls into the product)



Zip ESD uniform upper than name plate
(To avoid fiber of shirt falls into product)



Make sure that trousers/pants do not touch the ground

(To avoid accumulation of waste from outside)



Wearing Hairnet inside the cap



Do not roll up sleeve
(To avoid body hair and
fiber of shirt falls into
product)





Make sure the shirt is tucked in

(To prevent from static electricity and to avoid fiber of shirt falls into product)



[Attention points of work area]

1. To avoid any foreign matter (such as hair) comes into product, do not fix hair inside the area (use dressing room).

2. Do not touch hair because hair can attached to gloves and can cause foreign matter.

3. Wear glove after entering the area (process). (There is possibility that foreign matter accumulation if gloves was worn outside.

						Prepare	Check	Approve
05/23/2022	2	Change Photo using New ESD and include hairnet inside the cap	L. Famodulan	C. Luna	O. Merin	Λ		
09/09/2019	1	Transfer to new format, Update ESD uniform and Generalize Customer code	J. Lorzano	D. Cornero	O. Merin	Thom dilano	Ougus	Mei
06/01/2017	0	Initial issue.	A. Yocor	O. Merin	T. Sugiyama		C. Luna	O Merin
Eff./Rev. Date	Rev. No.	Details of change	Revise	Check	Approve	Est. date:	06/01	/2017

CONFIDENTIAL: @2017 NBC; all rights reserved. Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)

MASTER COPY