
						WORK INST						Ef	fectivity Date:		August 12, 2021 n/a WI-ENG-PDE-307		
			Process Name/Title:	,	SUB-	ASSEMBLY/ COM	TIUNIT	TY TESTER I	MACHIN	NE SET-	UP	Va	alidity Date:		n/a		
			Product Name/Code:	240B/970A	1	17J613/17J711	Custom	ier:	NB	С		Do	ocument No.:		WI-ENG-PDE-	307	
			Purpose:	PI	ROTOTYI	PE	PRE-LAU	INCH	MASS	PRO		Re	evision No.:	0	Page No.:	1 of 5	
		1										1		1			
PARTS:		n/a											JIG:	1. Inspection	on tester jig and ma	chine	
NO	0.	PF	OCESS NAME			WORK PR	OCEDU	RE/ ILLUSTRA	TION				TOOLS/PPE	(QUALITY POIN	TERS	
1	1		Power cord insertion				po ur PI	Connect the power ower socket on the nit. lug the power cord ower outlet.	back of the	e main		i	Safety Instruction Be sure to wear required personal protective equipment during operation (gloves, finger cots, etc.) Housekeeping 1. Maintain and always practice 5's.	1. Make sulunit is set to 2. Before co	re that the power sto "OFF". connecting cables a power of the main	vitch on the main	
2	2		Inspection cable attachment	MAIN U	NIT	INSPECTION A B	A JIG	CLIP	cable mair jig). first Push	onnect the ir e (cable con unit and th Attach to the the cable to on both side	necting the e inspection main unit inspection journal move the		2. Personal things on the workplace is prohibited. Keep it in your locker. Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.		g cable insertion ion must A to A and	iB to B.	
ļ .		1				Revision History		Т					Prepared by F	Reviewed by	Approved by	Noted by	
08/12/21		Initial issu	ue .						M. Catapang	C. Villanueva	A. Shimamura	A. Arañe	Min satural C	. Vilianueva	A. Shimamura	A. Arañes	
Eff. Date					Details of	f Change			Prepared	Checked	Approved	Noted		ıst 12, 2021	•		

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.


		Effectivity Date:	fectivity Date: August 12, 202					
Process Name/Title:	SUB-AS	SEMBLY/ CONTIN	UITY TESTE	ER MACHINE SET-UP	Validity Date:		n/a	l
Product Name/Code:	240B/970A /	17J613/17J711	Customer:	NBC	Document No.:		WI-ENG-P	DE-307
Purpose:	☐ PROTOTY	PE E	PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	2 of 5



CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC

			WORK INSTRU	CTION		Effectivity Date:	Į.	August 1	12, 2021
rocess Name/Title:	SUB	-ASS	EMBLY/ CONTI	NUITY TESTE	R MACHINE SET-UP	Validity Date:		n/a	3
roduct Name/Code:	240B/970A	1	17J613/17J711	Customer:	NBC	Document No.:	WI	I-ENG-F	PDE-307
urpose:	☐ PF	ROTOTYF	PE	PRE-LAUNCH	MASSPRO	Revision No.:	0 Pag	je No.:	3 of 5



CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.



			WORK INSTRU	Effectivity Date:		August 12, 2021			
Process Name/Title:	SUB	-ASS	Validity Date:		n/a				
Product Name/Code:	240B/970A	1	17J613/17J711	Customer: NBC Doc		Document No.:		WI-ENG-	PDE-307
Purpose:	☐ PF	ROTOTY	PE	PRE-LAUNCH	MASSPRO	Revision No.:	0	Page No.:	4 of 5

PARTS: 1. Inspection tester jig and machine JIG n/a PROCESS NAME **WORK PROCEDURE/ ILLUSTRATION** TOOLS/PPE **QUALITY POINTERS** NO. set 1. Press the set button using right index finger to proceed on selection of the product number. 1. Check the correct setting of product Product number setting n/a number Knob 2. Turn the knob using left hand to select another product number.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.



			WORK INSTRU		Effectivity Date:		August	12, 2021	
Process Name/Title:	SUB	-ASS	SEMBLY/ CONTIN	Validity Date:		n/a			
Product Name/Code:	Code: 240B/970A / 17J613/17J71			Customer:	NBC	Document No.:		WI-ENG-	PDE-307
Purpose:	☐ PF	ROTOTY	PE	PRE-LAUNCH	☐ MASSPRO	Revision No.:	0	Page No.:	5 of 5

1. Inspection tester jig and machine PARTS: n/a JIG PROCESS NAME **WORK PROCEDURE/ ILLUSTRATION** TOOLS/PPE **QUALITY POINTERS** NO. MODEL NMC12 17J711-7051P 3. Press again the Set button using right index finger to start the Wiring Test. Product number setting 1. Check the correct setting of product n/a (Continuation) number **ESCAPE** MODEL NMC1 4. If need to return to setting of product number or MENU, press the ESC button.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.