EE30220 MECHATRONIC DESIGN PROJECT

ALGORITHMS - EXAMPLE EXERCISE 6

JÉRÉMY BONVOISIN



Nov. 8TH, 2019

ALGORITHM #2








































































ISSUES

- how do we sort magnets per x coordinate?
- not clever to cut the plane along the same direction each time. Better to alternate, vertical, horizontal
- we need to close the loop at the end

ALGORITHM #3














































































ISSUES

- vertical and horizontal cuts are abitrary and may not be optimal
- how to identify whether a magnet has been linked more than one time already?
- how to identify the two nodes that need to be linked so we can close the loop?

ALGORITHM #4

