$$V_s = 12V$$
  $R_1 = 1 k\Omega$   $V_2 = 12V$   $R_2 = 5 k\Omega$  Potentiometer