

ABNT ISO 3758:2013





Classes



Não lavar

"1-0"



40°C, Normal

"1-40-0"



40°C, Suave

"1-40-1"



40°C, Muito Suave

"1-40-2"