

# Application Note AN1014-00, 2014-10-10 Error Code





### **Notice**

### **Registered Trademark**



ARETE mobile is launched by PHYCHIPS Inc. for mobile device and currently registered worldwide with its ARETE mobile trade mark legally protected by law.

© 2014 PHYCHIPS Inc. All rights reserved.

This document is produced by PHYCHIPS Inc. and protected by Copyright Laws. Please note that there may be possible mistake or omission of information in this document.



## Revision History

Version	Date	Changes	
00	2014-10-10	Initially released	



ARETE POP firmware had been updated to report the extended error code. The new RCP packet is assigned 3 bytes for error code while the legacy packet has 1 byte of error code. The first byte of error code is the same as the legacy error code for backward compatibility. Next 2 bytes have more information.

Preamble	Msg Type	Code	PL (MSB)	PL (LSB)	Error Code	End Mark	CRC-16
0xBB	0x01	0xFF	0x00	0x01	[0]	0x7E	0xNNNN



Preamble	Msg Type	Code	PL (MSB)	PL (LSB)	Error Code	Error Code	Error Code
0xBB	0x01	0xFF	0x00	0x02	[0]	[1]	[2]
End Mark	CRC-16						
0x7E	0xNNNN						

Android and iPhone Api also report 3 bytes error code.

ios	@optional			
103	- (void) failureReceived:(NSData *)errCode			
Android	void onFailureReceived(final int[] errCode)			
Description	You can override this method to perform additional tasks associated with RCP error.			
	errCode[0]: RCP error code.			
	- 0x09: Failure to read the tag memory			
	- 0x0B: 'startReadTags' in Operation			
	- 0x0D: Not in mode 'Read Type C Tag ID Multiple'			
	- 0x0E: Invalid parameter			
	- 0x10: Failure to write data			
Parameters	- 0x12: Failure to kill a tag			
	- 0x13: Failure to lock a tag			
	- 0x15: Failure to read a tag			
	- 0x18: Not supported command			
	- 0xFF: CRC Error			
	errCode[1]: Command code			
	errCode[2]: More information			
Return Value	None			

- The third byte gives more information shown below.
- √ 0x00 0x0F : EPC Gen2 V2.0 Error Message

0x00 : Other error

0x01: Not supported

0x02: Insufficient privileges

0x03: Memory overrun

0x04: Memory locked

0x05 : Crypto suite error

0x06: Command not encapsulated

0x07: ResponseBuffer overflow

0x08 : Security timeout

0x0B: Insufficient power

0x0F: Non-specific error

√ 0x10 – 0x7F : Vendor Specific Error Code

0x11: Sensor scheduling configuration (EM4325)

0x12 : Tag busy (EM4325)

0x13: Measurement type not supported (EM4325)

√ 0x80 – 0x8F : [PHYCHIPS] Protocol Error

0x80: FAIL\_NO\_TAG\_DETECTED

0x81: FAIL HANDLE ACQ

0x82: FAIL PASSWORD

√ 0x90 – 0x9F : [PHYCHIPS] Modem Error

0x90: FAIL\_CRC\_ERROR

0x91: FAIL RX TIMEOUT

- √ 0xA0 0xEF : Reserved
- √ 0xF0 0xFF : [PHYCHIPS] Common Error

0xF0: FAIL NOT SUPRT CMD

0xF1: FAIL UNDEF CMD

0xF2: FAIL\_INVALID\_PARM

0xF3: FAIL TOOHIGH PARM

0xF4: FAIL\_TOOLOW\_PARM

0xF5: FAIL READ AUTO OP

0xF6: FAIL\_NO\_AUTO\_MODE

0xF7: FAIL\_RDR\_RESET

0xF8: FAIL GET LAST RSP

0xF9: FAIL\_CTRL\_TEST

0xFF: FAIL CMD



#### **ARETE mobile Customer Service**

Phone: + 82 42 864 2402 Fax: + 82 42 864 2403

Email: sales@phychips.com

#### Address

PHYCHIPS Inc.

#104 Migun Technoworld 2, 187 Techno 2-ro, Yuseong-gu, Daejeon, Korea 305-500

#### **Working Day and time**

Monday to Friday 09:00~18:00(Korean Time, GMT Time + 9 hours)

#### **Local Customer Service**

Please contact where you buy.