

Explosion Chamber

Dimensions (Internal): 900 x 900 x 900 [mm]

Material: Steel

LU-Measurement Chain

Pressure Transducer

Model
Kistler 7061B

Type
Piezoelectric

Charge Amplifier

Model
Kistler 5067A

DAQ System

Model
Datalogger
TPCE-0216-8S

Computer
(Data Processing)

DBI-Measurement Chain

Pressure Transducer

Model
Kistler 601CAA

Type
Piezoelectric

Charge Amplifier & DAQ Unit

Model
Kistler 5165A4

Computer
(Data Processing)

Kistler-Measurement Chain

Pressure Transducer

Model
Kistler 7061B/ 601CAA

Type
Piezoelectric

X

Charge Amplifier & DAQ Unit

Model
Kistler XXX

Computer
(Data Processing)