

EXDA Metadata Report

Project: VH2D-Project

Generated: 2026-05-24 20:53:21

Includes: Plan, DAQ Systems, Sensors Mapping, Gas Mixing

Responsible Researcher: PhD Student Javier I. Camacho

Project Objective:

LU / DBI / Kistler pressure DAQ systems characterisation.

Project Description:

The primary objectives of the experiments are:

1. Internal Over-pressure Development

Measurement of internal over-pressure development during vented hydrogen deflagrations in a partially confined enclosure for homogeneous flammable hydrogen-air mixtures with hydrogen concentrations up to 19 vol.%.

2. Flame Propagation (Under Consideration)

Measurement of flame propagation characteristics, including potential estimation of flame time-of-arrival (TOA) at selected locations.

3. Instrumentation Evaluation

Evaluation and cross-comparison of different pressure measurement systems and data acquisition configurations, including sensor characteristics and the influence of measurement chain dynamics (e.g., time constant (τ) effects, sampling rate).

4. Measurement Uncertainty Factors

Investigation of experimental factors that may affect the accuracy and reliability of pressure measurements, including structural vibration effects and thermal protection methods.

5. Venting Behaviour

Investigation of vent opening behaviour and the influence of vent rupture mechanisms on pressure development, including comparison between pressure-driven thin-film rupture and controlled vent opening using a hot-wire cutting system.



EXDA Plan Export - Experiment_Plan_v000

Responsible Researcher: PhD Student Javier I. Camacho

Objective: LU / DBI / Kistler pressure DAQ systems characterisation.

Start: 2026-05-25 | Deadline: 2026-05-29

Total Experiments: 18

Generated: 2026-05-24 20:53:20

Group: Prep

Group Objective: -

Run	Done	Schedule	H2 (%)	Ignition	Vent	P0 (Pa)	T0 (K)	Files	File Path (Raw_Data Folder)
Prep-01	No	2026-05-25	12	back	Thin Plas.	101325	293	6	Prep-01/Prep-01-DAQ-1 Prep-01/Prep-01-DAQ-2 Prep-01/Prep-01-DAQ-3 Prep-01/Prep-01-H2CM-1 Prep-01/Prep-01-H2CM-2 Prep-01/Prep-01-H2CM-3
Prep-02	No	2026-05-25	12			101325	293	0	-

Group: VH2D-01

Group Objective: Vented deflagration concentration series (Hotwire)

Run	Done	Schedule	H2 (%)	Ignition	Vent	P0 (Pa)	T0 (K)	Files	File Path (Raw_Data Folder)
VH2D-01-01	No	2026-05-26	12	Back	Thin Plas.	101325	293	0	-
VH2D-01-02	No	2026-05-26	12			101325	293	0	-
VH2D-01-03	No	2026-05-26	14			101325	293	0	-
VH2D-01-04	No	2026-05-26	14			101325	293	0	-
VH2D-01-05	No	2026-05-26	16			101325	293	0	-
VH2D-01-06	No	2026-05-26	16			101325	293	0	-
VH2D-01-07	No	2026-05-26	18			101325	293	0	-
VH2D-01-08	No	2026-05-26	18			101325	293	0	-

Group: VH2D-02

Group Objective: Vented deflagration concentration series (NO Hotwire)

Run	Done	Schedule	H2 (%)	Ignition	Vent	P0 (Pa)	T0 (K)	Files	File Path (Raw_Data Folder)
VH2D-02-01	No	2026-05-26	12			101325	293	0	-
VH2D-02-02	No	2026-05-26	14			101325	293	0	-
VH2D-02-03	No	2026-05-26	16			101325	293	0	-

VH2D-02-04	No	2026-05-26	18			101325	293	0	-
------------	----	------------	----	--	--	--------	-----	---	---

Group: VH2D-03

Group Objective: -

Run	Done	Schedule	H2 (%)	Ignition	Vent	P0 (Pa)	T0 (K)	Files	File Path (Raw_Data Folder)
-----	------	----------	--------	----------	------	---------	--------	-------	-----------------------------

VH2D-03-01	No	2026-05-28	18			101325	293	0	-
------------	----	------------	----	--	--	--------	-----	---	---

Group: VH2D-04

Group Objective: -

Run	Done	Schedule	H2 (%)	Ignition	Vent	P0 (Pa)	T0 (K)	Files	File Path (Raw_Data Folder)
-----	------	----------	--------	----------	------	---------	--------	-------	-----------------------------

VH2D-04-01	No	2026-05-28	18			101325	293	0	-
------------	----	------------	----	--	--	--------	-----	---	---

Group: VH2D-05

Group Objective: -

Run	Done	Schedule	H2 (%)	Ignition	Vent	P0 (Pa)	T0 (K)	Files	File Path (Raw_Data Folder)
-----	------	----------	--------	----------	------	---------	--------	-------	-----------------------------

VH2D-05-01	No	2026-05-29				101325	293	0	-
------------	----	------------	--	--	--	--------	-----	---	---

Group: VH2D-06

Group Objective: -

Run	Done	Schedule	H2 (%)	Ignition	Vent	P0 (Pa)	T0 (K)	Files	File Path (Raw_Data Folder)
-----	------	----------	--------	----------	------	---------	--------	-------	-----------------------------

VH2D-06-01	No	2026-05-29				101325	293	0	-
------------	----	------------	--	--	--	--------	-----	---	---

EXDA DAQ Systems Export

Project: VH2D-Project

Responsible Researcher: PhD Student Javier I. Camacho

Total DAQ Systems: 5

Reference PDF: LU-DBI Measurement Chain (frontend/public/LU-DBI_MeasurementChain_v001.pdf)


Reference PDF: Mixture Sampling Sub-System (frontend/public/MixtureSampling_Sub-System_000.pdf)

Generated: 2026-05-24 20:53:20

Name	Quantity	Vendor	Model	Serial	Fs (Hz)	Ch	Owner	Last Cal.	Cal Cert ID	Active	Notes
DAQ-1	pressure	Kistler	-	-	-	8	LU	-	-	Yes	-
DAQ-2	pressure	Kistler	-	-	-	4	DBI	-	-	Yes	-
DAQ-3	pressure	Kistler	-	-	-	4	Kistler	-	-	Yes	-
DAQ-4	pressure	Kistler	-	-	-	8	Kistler	-	-	Yes	-
H2CM	concentration	JCT	JTCD-300	14362	1	-	LU	2025-07-21	-	Yes	-

DAQ Reference Diagram - LU-DBI Measurement Chain

Source: frontend/public/LU-DBI_MeasurementChain_v001.pdf




Explosion Chamber


Dimensions (Internal): 900 x 900 x 900 [mm]

Material: Steel


LU-Measurement Chain



DBI-Measurement Chain




Kistler-Measurement Chain



DAQ Reference Diagram - Mixture Sampling Sub-System

Source: frontend/public/MixtureSampling_Sub-System_000.pdf



EXDA Sensors Mapping Export

Project: VH2D-Project

Responsible Researcher: PhD Student Javier I. Camacho

Total Groups: 7

Total Sensor IDs: 11

Total Sensor Mappings: 12

Sensor Mounting Reference File: frontend/public/SensorMountingLocation-000.pdf

Generated: 2026-05-24 20:53:20

Group: Prep

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
Prep	P1	pressure	DAQ-1	CH1	m123	75 pC/bar	1L	(1,1,1)	recessed	Yes	No	-	Complete
Prep	P2	pressure	DAQ-1	CH2	-	- pC/bar	4L	(-, -, -)	flush	Yes	No	-	Incomplete
Prep	P3	pressure	DAQ-1	CH3	-	- pC/bar	2L	(-, -, -)	other	Yes	Yes	-	Incomplete
Prep	P4	pressure	DAQ-1	CH4	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
Prep	P5	pressure	DAQ-2	CH1	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
Prep	P6	pressure	DAQ-2	CH2	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
Prep	P7	pressure	DAQ-2	CH3	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
Prep	P8	pressure	DAQ-3	CH1	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
Prep	Trig-1	voltage	DAQ-1	CH5	-	- pC/bar	-	(-, -, -)	other	Yes	No	M-Duino	Complete
Prep	Trig-2	voltage	DAQ-2	CH4	-	- pC/bar	-	(-, -, -)	other	Yes	No	M-Duino	Complete
Prep	Trig-3	voltage	DAQ-3	CH2	-	- pC/bar	-	(-, -, -)	other	Yes	No	M-Duino	Complete

Group: VH2D-01

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-01	P8	pressure	Kistler	-	-	- pC/bar	-	(-, -, -)	flush	Yes	No	-	Incomplete
			LabAmp										

Group Reference Note: same configuration as preparation group

Group: VH2D-02

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-02	-	-	-	-	-	-	-	-	-	-	-	-	Reference

Group Reference Note: same configuration as preparation group

=====
Group: VH2D-03

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-03	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													

=====
Group: VH2D-04

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-04	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													

=====
Group: VH2D-05

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-05	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													


=====
Group: VH2D-06

Group	Sensor	Qty	DAQ	Ch	S/N	Sensitivity	Location	Coord.(x,y,z)m	Mount	Active	Blind	Trig Method	Status
VH2D-06	-	-	-	-	-	-	-	-	-	-	-	-	Reference
Group Reference Note: same configuration as preparation group													

Sensor Mounting Reference Diagram

Source: frontend/public/SensorMountingLocation-000.pdf

Pressure Sensor Location Mapping Overview



EXDA Gas Mixing Export

Project: VH2D-Project
Responsible Researcher: PhD Student Javier I. Camacho
Total Records: 0
Generated: 2026-05-24 20:53:20
MATLAB Verified: Yes
Verification File A: scripts/GasMixingVerificationFiles/H2_MFC_Fill_Calculator_v000.m
Verification File B: scripts/GasMixingVerificationFiles/AuxFcn_H2_MFC_FillCalculator_000.m

Shared Chamber Setup (applies to all runs unless noted otherwise):
L=- m, W=- m, H=- m, Pipes+/- m³, Hotwire+/- m³, Welded=- m³, Bolts=- m³, Vcorr=- L

Core Gas Mixing Results										
Group	Run/Test	H2%	Pch(Pa)	Tch(K)	H2(g)	H2inj(L)	MFC	t(s)	t(min)	Updated
-----+-----+-----+-----+-----+-----+-----+-----+-----+-----										