

EXDA Sensors Mapping Export

Project: VH2D-Project

Responsible Researcher: PhD Student Javier I. Camacho

Total Groups: 7

Total Sensor IDs: 8

Total Sensor Mappings: 9

Sensor Mounting Reference File: frontend/public/SensorMountingLocation-000.pdf

Generated: 2026-05-24 09:56:04

Group	Group Note	Sensor	Qty	DAQ	Ch	Serial	Sensitivity	Location	Coordinates	Mount	Active	Blind	Status
Group: Preparation													
Preparation	-	P1	pressure	DAQ-1	CH1	m123	75 pC/bar	1L	x=1, y=1, z=1	recessed	Yes	No	Complete
Preparation	-	P2	pressure	DAQ-1	CH2	-	- pC/bar	left wall	x=-, y=-, z=-	flush-mounted	Yes	No	Missing/Invalid (missing serial; invalid sensitivity)
Preparation	-	P3	pressure	DAQ-1	CH3	-	- pC/bar	blind/control channel	x=-, y=-, z=-	other	Yes	Yes	Missing/Invalid (missing serial; invalid sensitivity)
Preparation	-	P4	pressure	DAQ-1	CH4	-	- pC/bar	-	x=-, y=-, z=-	flush-mounted	Yes	No	Missing/Invalid (missing serial; invalid sensitivity)
Preparation	-	P5	pressure	DAQ-2	CH1	-	- pC/bar	-	x=-, y=-, z=-	flush-mounted	Yes	No	Missing/Invalid (missing serial; invalid sensitivity)
Preparation	-	P6	pressure	Kistler	-	-	- pC/bar	-	x=-, y=-, z=-	flush-mounted	Yes	No	Missing/Invalid (missing serial; invalid sensitivity)

ion			e	LabAmp					m	ounted			valid (missing DAQ channel; missing serial)
Preparat ion	-	P7	pressur e	Kistler LabAmp	-	-	- pC/bar	-	x=-, y=-, z=- m	flush-m ounted	Yes	No	Missing/In valid (missing DAQ channel; missing serial)
Preparat ion	-	P8	pressur e	Kistler LabAmp	-	-	- pC/bar	-	x=-, y=-, z=- m	flush-m ounted	Yes	No	Missing/In valid (missing DAQ channel; missing serial)

Group: VH2D-01

VH2D-01	same configuration as preparation	P8	pressur e	Kistler LabAmp	-	-	- pC/bar	-	x=-, y=-, z=- m	flush-m ounted	Yes	No	Missing/In valid (missing DAQ channel; missing serial)
---------	---	----	--------------	-------------------	---	---	----------	---	--------------------	-------------------	-----	----	--

Group: VH2D-02

VH2D-02	-	-	-	-	-	-	-	-	-	-	-	-	Reference only (no sensor changes)
---------	---	---	---	---	---	---	---	---	---	---	---	---	---

Group: VH2D-03

VH2D-03	-	-	-	-	-	-	-	-	-	-	-	-	-	Reference only (no sensor changes)

=====
Group: VH2D-04

VH2D-04	-	-	-	-	-	-	-	-	-	-	-	-	-	Reference only (no sensor changes)

=====
Group: VH2D-05

VH2D-05	-	-	-	-	-	-	-	-	-	-	-	-	-	Reference only (no sensor changes)

=====
Group: VH2D-06

VH2D-06	-	-	-	-	-	-	-	-	-	-	-	-	-	Reference only (no sensor changes)

Sensor Mounting Reference Diagram

Source: frontend/public/SensorMountingLocation-000.pdf

Pressure Sensor Location Mapping Overview

