

模具用加工材料品牌对照表
Comparison Table of Die and Mold Materials

为了使用安全
Read Following Precautions for Safe Use

分类 Classification	JIS	AISI	硬度 (HRC) Hardness	山阳特殊钢制 SANYO SPECIAL STEEL	大同特殊钢制 DAIDO STEEL	日本高周波钢业 NIHON KOSHUHA STEEL	日立金属 HITACHI METALS	不二越 NACHI FUJIKOSHI	乌德霍尔姆 UDDEHOLM	伯乐 BOHLER
钨钢类 Tungsten type	SKH2	T1	62~			H2	YHX2	SKH2		S200
	SKH3	T4	64~			H3		SKH3		S305
	SKH4	T5	64~			H4		SKH4		
	SKH10	T15	64~			HV5				
钼类 Molybdenum type	SKH51	M2	55-65	QH51	MH51	H51	YXM1	SKH9		S600 S614 S401
	SKH52	M3-1	57-66			H52		HM31		
	SKH53	M3-2	64~			HV1				S607
	SKH54	M4	64~			HV2		HM4		
	SKH55		60-66			HM35	YXM4	HM35		S705
	SKH56	M36	60-66			HM36		HM36		
	SKH57		62-67			HV10	XVC5	HS93R		S700
	SKH58	M7	64~			HM3		HM7NN		S400
	SKH59	M42	52-67			HM42	YXM42	HM42		S500
	其它 Other					S70	YXM27 YXM60	HS53M HS97R HM1 HMT12 HM33 SKH9D DURO-SP		
矩阵类 Matrix type	矩阵类 Matrix type		45-65	QHZ	DRM1 DRM2 DRM3 MH85	KMX1 KMX2 KMX3	YXR3 YXR33 YXR7	DURO-FZ DURO-F1 DURO-F3 DURO-F7 DURO-V2 DURO-V5		W360
粉末类 Powdered type	SKH40		58-70	SPM30	DEX40		HAP40	FAX38	VANADIS30	S590
	其它 Other		58-70	SPM23 SPM60 SPMR8 SPMV6 SPMX4N	DEX20 DEX60 DEX-M1 DEX-M3		HAP10 HAP50 HAP72 HAP5R	FAX31 FAX40 FAX55 FAXG2	VANADIS23 VANADIS60	S290 S390 S690 S790

安全注意事项Attention on Safety

- 从铣刀盒拿取刀具时，请充分注意避免刀具弹出，不可用手直接触碰刀刃。
When removing tools from cases, be careful of getting-out of tools and don't touch directly the cutting edges.
- 请注意不可用手直接接触刀刃。
Never touch the cutting edges directly with bare hand.
- 使用刀具时可能会引起损伤，请务必使用罩盖、防护镜等器具。
Use safety covers and eye protection, as tools may be broken.
- 刀夹等必须与刀具及加工内容相匹配。
刀具必须牢固地固定在刀夹上，避免发生振刀。
Use holders, etc. that match the tools and nature of the processing operations.
The tool should be firmly attached to the holder to prevent shaking.
- 请牢固地固定工件。
The work materials clamp firmly.
- 加工前请确认刀具和工件的尺寸。
Make sure of dimensions of tools and work pieces before starting operation.
- 应根据工件和所使用的机床调整切削条件。
It is necessary to adjust conditions according to the dimensions of work materials and the machine.
- 请根据用途选用切削油。使用切削油时，可能会因加工时产生的火花或损伤导致起火乃至发生火灾。请务必采取防火措施。
Select a cutting fluid appropriate to the particular usage. Using a non-water cutting fluid could lead to fires due to sparks generated during processing or heat caused by breakage. Ensure that you take proper fire-prevention measures.
- 使用中若发生异常（切削声响、冒烟），请立即停止机床。
If abnormal sound, etc. occurs during processing, stop the machine immediately.
- 请勿对刀具进行改造。
Don't modify tools.

※为了改进和提高产品，本产品目录中刊登的产品规格可能变更.恕不预告。
※Specifications may change without notice for improvement.