ASSEMBLY CHALLENGES

The wheels on the servos

Figuring out that small screws fit into parts of the wheels was important, as it allowed the scoop to attach to the arm

designed to fit the wheel, there was no arm with screws

Since a part could be need to attach the base



Drilling holes

Some components needed holes drilled into them so they could be screwed into

After a few attempts on practice parts, the drilling and screwing process was made easy



