
6. HOPPER CELEBRATION



- The magnets worked well, but I was still skeptical of the stand
- I removed the stand, but kept the magnets, and ran more tests
 - I found that the hopper went farther without the stand, and that the magnets helped bring the launch angle closer to 45 degrees
- I then added an additional rubber band to the bottom part of the hopper, with the hopes of increasing the traction
 - This was a success, as the hopper went farther with this rubber band on the bottom
- My hopper was then ready to perform at the hopper celebration
 - I was pleased with the hop at the hopper celebration

